	RTMENT OF THE INT		Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. NM-7724	
SUNDRY N	IOTICES AND REPOR		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
OIL GAS OTH	ER	DEC 26 1984	7. UNIT AGREEMENT NAME	
NAME OF OPERATOR		O. C. D.	8. FARM OR LEASE NAME	
CASA PETROLEUM, INC.		ARTESIA, OFFICE	HIGHWEST FEDERAL 9. WBLL NO.	
105 North 6th, A	Artesia, New Mexico	88210	1	
LOCATION OF WELL (Report locat See also space 17 below.) At surface	tion clearly and in accordance wit	th any State requirements.*	10. FIELD AND POOL, OR WILDCAT	
1650' FSL & 330' FWL of Section		(NW↓SW↓) (Unit L)	11. SEC., T., E., M., OB BLE. AND SURVEY OR ABBA Sec. 7-165-30E	
. PERMIT NO.	15. ELEVATIONS (Show whet 3756 !		12. COUNTY OF PARISE 13. STATE Eddy NM	
Check	Appropriate Box To Indice	ate Nature of Notice, Report, or C	Other Data	
NOTICE OF 1	INTENTION TO :	susabq	BUBARQUENT REPORT OF :	
TEST WATER SHUT-OFF	PULL OR ALTER CABING	WATER SHUT-OFF	BEPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	SHOOTING OR ACIDIZING	- ALTEBING CABING	
REPAIR WRUL	CHANGE PLANS	(Other)	of multiple completion on Well	
proposed work. If well is di		e locations and measured and true vertica	including estimated date of starting any al depths for all markers and sones perti-	
TD 3435' (PB 2875 Pursuant to telep	'). Perfora	ations from 2449 - 2764'. etween Patch Karr and Bob	il depths for all markers and sones perti-	
TD 3435' (PB 2875 Pursuant to telep well was plugged	'). Perfora hone conversation be on 5-30-84 as follow	ations from 2449 - 2764'. atween Patch Karr and Bob ws:	il depths for all markers and sones perti-	
TD 3435' (PB 2875 Pursuant to telep well was plugged	'). Perform hone conversation be on 5-30-84 as follow s cement from 2800 -	ations from 2449 - 2764'. atween Patch Karr and Bob ws:	il depths for all markers and sones perti-	
TD 3435' (PB 2875 Pursuant to telep well was plugged Set 35 sacks Filled hole	'). Perform hone conversation be on 5-30-84 as follow cement from 2800 - with mud.	ations from 2449 - 2764'. atween Patch Karr and Bob ws:	il depths for all markers and sones perti-	
TD 3435' (PB 2875 Pursuant to telep well was plugged Set 35 sacks Filled hole Shot off 4½"	'). Perform hone conversation be on 5-30-84 as follow cement from 2800 - with mud. casing at 1108'.	ations from 2449 - 2764'. etween Patch Karr and Bob ws: 2300'.	il depths for all markers and sones perti-	
TD 3435' (PB 2875 Pursuant to telep well was plugged Set 35 sacks Filled hole Shot off 4½" Set 25 sacks	'). Perform hone conversation be on 5-30-84 as follow cement from 2800 - with mud. casing at 1108'. cement from 1108 -	ations from 2449 - 2764'. etween Patch Karr and Bob ws: 2300'. 1026'.	il depths for all markers and sones perti-	
TD 3435' (PB 2875 Pursuant to telep well was plugged Set 35 sacks Filled hole Shot off 4½" Set 25 sacks Set 50 sacks	'). Perform hone conversation be on 5-30-84 as follow cement from 2800 - with mud. casing at 1108'. cement from 1108 - s cement from 500 - 3	ations from 2449 - 2764'. etween Patch Karr and Bob ws: 2300'. 1026'. 342'.	il depths for all markers and sones perti-	
TD 3435' (PB 2875 Pursuant to telep well was plugged Set 35 sacks Filled hole Shot off 4½" Set 25 sacks Set 50 sacks WOC for 2 ho	'). Perform hone conversation be on 5-30-84 as follow cement from 2800 - with mud. casing at 1108'. cement from 1108 - s cement from 500 - 3 ours and tagged plug.	ations from 2449 - 2764'. etween Patch Karr and Bob ws: 2300'. 1026'. 342'.	il depths for all markers and sones perti-	
TD 3435' (PB 2875 Pursuant to telep well was plugged Set 35 sacks Filled hole Shot off 4½" Set 25 sacks Set 50 sacks WOC for 2 ho	'). Perform hone conversation be on 5-30-84 as follow cement from 2800 - with mud. casing at 1108'. cement from 1108 - s cement from 500 - 3 ours and tagged plug. cement from 60' - s	ations from 2449 - 2764'. etween Patch Karr and Bob ws: 2300'. 1026'. 342'.	il depths for all markers and sones perti-	
TD 3435' (PB 2875 Pursuant to telep well was plugged Set 35 sacks Filled hole Shot off 4½" Set 25 sacks Set 50 sacks WOC for 2 ho Set 20 sacks Set Dry Hole	'). Perform hone conversation be on 5-30-84 as follow cement from 2800 - with mud. casing at 1108'. cement from 1108 - cement from 500 - 3 burs and tagged plug. cement from 60' - s Marker.	ations from 2449 - 2764'. etween Patch Karr and Bob ws: 2300'. 1026'. 342'.	Pitschke on 5-29-84,	
TD 3435' (PB 2875 Pursuant to telep well was plugged Set 35 sacks Filled hole Shot off 4½" Set 25 sacks Set 50 sacks WOC for 2 ho Set 20 sacks Set Dry Hole	'). Perform hone conversation be on 5-30-84 as follow cement from 2800 - with mud. casing at 1108'. cement from 1108 - cement from 500 - 3 burs and tagged plug. cement from 60' - s Marker.	ations from 2449 - 2764'. etween Patch Karr and Bob ws: 2300'. 1026'. 342'.	Pitschke on 5-29-84, $p_{st} = \frac{1}{2} \frac{1}{$	
TD 3435' (PB 2875 Pursuant to telep well was plugged Set 35 sacks Filled hole Shot off 4½" Set 25 sacks Set 50 sacks WOC for 2 ho Set 20 sacks Set Dry Hole	'). Perform hone conversation be on 5-30-84 as follow cement from 2800 - with mud. casing at 1108'. cement from 1108 - cement from 500 - 3 ours and tagged plug. cement from 60' - s Marker.	ations from 2449 - 2764'. etween Patch Karr and Bob ws: 2300'. 1026'. 342'. surface.	Pitschke on 5-29-84, $\rho_{est} = \frac{T}{r} \frac{2}{r} \frac{2}{r} \frac{1}{r} \frac{1}$	

...

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.