

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

U.S. COMMISSION
SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

OCT 18 1991

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ Plug & Abandon	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR McClellan Oil Corporation ✓ 505-622-3200	8. FARM OR LEASE NAME Simmons Federal
3. ADDRESS OF OPERATOR P.O. Drawer 730 Roswell, NM 88202-0730	9. WELL NO. #5
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1850' FSL & 1850' FEL	10. FIELD AND POOL, OR WILDCAT W. Henshaw Grayburg
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GM, etc.) 3697' GL
12. COUNTY OR PARISH Eddy	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8 5/8 395' - Circulated 2 3/8 tbg
4 1/2 9.5# 2605' 65 sx cmt
TOC 2050' Perfs - 2077'-2575'

1. Run CIBP to 2020' & set - Load hole w/heavy gel H₂O.

2. Shoot csg off at 2000' & pull out of hole.

3. 1st plug 2020' to 1920' 30 sx
2nd plug 1100' to 1000' 30 sx
3rd plug 445' to 345' Tag 30 sx
4th plug 60' to Surface 20 sx
8 5/8" w/cmt.
} fill csg. from ~250' to surface.

Clean location & install dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Drlg. & Comp. Engineer

DATE 5-23-91

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE 10/8/91

*See Instructions on Reverse Side