Form 3160- 5 November 1983) Formerly 9331;	UNITE STATE DEPARTMENT OF THE BUREAU OF LAND MAN		PLICI Budg Expires on 5. LEASE D	approved. et Bureau No. 1004-013 res August 31, 1985 resignation and emilal no. -0559945	_ 451
	DRY NOTICES AND REP form for proposals to drill or to deeper Use "APPLICATION FOR PERMIT_"	n or plug back to a different reserv		W. ALLOTTEE OR TRIBE MAX	E
		RECEIVED BY	7. UNIT 401	7. UNIT AGEBEMENT NAME	
2. NAME OF OPERATOR		AUG 15 1985		8. PARM OR LEASE NAME	
METEX PIPE & SUPPLY		O. C. D.		Sunburst Federal	
3 ADDRESS OF OPERATO		ARTESIA, OFFICE	U. WALL NO	9. WELL NO.	
POB 1037 Artesia, NM 88210 ARIESIA, OFFICE 4 DOCATION OF WART (Report location clearly and in accordance with any State requirements. ⁴ See also space 17 below) At aurfain				10. FIELD AND POOL, OR WILDCAT N. Sq. Lake GB, SA	
3603' FNL & 2310 H			11. SBC., T.	11. SEC., T., B., M., OB BLK. AND SERVET OF AREA	
	(Lot 10)			16S-R31E	
14 - Harlester De	15. ELEVATIONS (Show 4065.21 GL	whether DF, BT, GR, etc.)	12. COUPTY Edd	t or parish 18. State dy NM	
14	Check Appropriate Box To Ir	dicate Nature of Notice, Rep	port, or Other Data		
	NOTICE OF INTESTION TO:	1	SUBSEQUENT REPORT	o r :	
TEST 8 - 78 80 7-0	PULL OR ALTER CASING	WATER BHUT-OFF		REPAIRING WELL	
FEA TERE THEAT	NULTIPLE COMPLETE	FRACTURE TREATS	IENT	ALTERING CARING	
SH(907) (m. 1002)	ABANION	BEOOTING OR ACH	-	ABANDON MENT [®]	
1883:488-19-2 1885:19-2	CHANGE PLANE		(Other) Plug Back & Run Casing XX (Nors: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		
12 IASCERE PROPORTS O proposed w r. 11 nent to this work.)	R CONTREETED OFFICATIONS (Clearly state r well is directionally drilled, give subar	Il pertinent details, and give perti-	pent dates lacinding ast	timated date of starting an	n.g. ti-
tor Cas Moo Cas	t Howco 50-Sx Cmt plug per BLM requirement. ing, 1-Howco 5½" Float del "RTS" E.C.P. (Open H sing, 1-Howco 5½" DV Too	Run 1-Howco 5½" Float Collar, 1-Jt.(24.27') ole) Inflatable Packes 1, 93-Jts. 17# LT&C Ca	Shoe, 1-Jt.(33 5 ¹ / ₂ " 17# LT&C C r, 1-Jt. (32.57 asing. (1st 20	3.08') 5½" 17# L1 Casing, 1-Lynes 5 7') 5½" 17# LT&C 200' 5½" Sand-Bla	Г&C 5쿨"

Float Shoe set at 3138', top of Lynes E.C.P. set at 3066' and top of Howco DV Tool set at 3039'. Open hole TD was 3548 and PBTD will be approx. 3039'. Note that Lynes $5\frac{1}{2}$ " E.C.P. was set at 3066' in first good gauge hole. Pump 50-Sx. Howco "H" Cement Plug with 3% CaCl thru $5\frac{1}{2}$ " Csg. and set Lynes E.C.P. Packer at 3066'. Opened DV Tool and circulated for 1-hour. Circulated 2-3sks. cement out of hole. Pumped Cement thru DV Tool as follows: 600-Sxs. Howco Lite with 15# NaCl + $\frac{1}{4}$ # Flocele, 250-Sxs. Howco "C" with 6# NaCl + 0.2 CFR3. Bumped Plug to 2200# & held for 15-min OK. <u>Circulated</u> 10-Sxs. Cmt. to pits.

Plans are to test the Queen Zone 2670-80' in approximately 1-week.

SIGNED MC	ntin B, Muncy	TITLE d/b/a Metex Pipe & Suppl	Y DATE	8-2-85
	ACCEPTED FOR RECORD) TITLE	D ATE	
	AUG 14 1985			
	•	See Instructions on Reverse Side		

Instructions

Gensral: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

State or Federal office for specific instructions. Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not scaled off by cement or otherwise; depths (op and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

