

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR...  
(Other Instructions on re-...)  
RECEIVED

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different use.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐  
2. NAME OF OPERATOR  
McClellan Oil Corporation ✓ 505-622-3200  
3. ADDRESS OF OPERATOR  
P.O. Drawer 730 Roswell, NM 88202  
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface  
990' FEL & 330' FNL

CARLE...  
AREA...  
RECEIVED

MAR 15 1991

O. C. D.  
ARTESIA, OFFICE

5. LEASE DESIGNATION AND SERIAL NO.  
NM-41642 ✓  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
Exxon Federal ✓  
9. WELL NO.  
#1  
10. FIELD AND POOL, OR WILDCAT  
High Lonesome  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 29-T16S-R29E  
12. COUNTY OR PARISH  
Eddy  
13. STATE  
NM

14. PERMIT NO.  
15. ELEVATIONS (Show whether DF, RT, GN, etc.)  
3626' GL

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other) ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
ABANDON\* ☒  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☐  
SHOOTING OR ACIDIZING ☐  
(Other) ☐  
REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Propose to Plug & Abandon: 8 5/8" set at 254' - cmt circulated  
5 1/2" set at 2000' - TOC 1000'  
Perfs 1849' - 1901' 11 Hole

- A. Propose to circulate hole w/A 10PPG mud.
- B. Plug #1 1800'-1950' 30 sx (covers Penrose Perfs) [TAG]
- C. Plug #2 950'-1050' 25 30 sx Tag plug
- D. Plug #3 200'- 300' 25 30 sx
- E. Plug #4 Surface-60' (in 5 1/2" & in 8 5/8" annulus).

Will install dry hole marker.

All csg to be left in hole.

run 1" in hole to 300'; attempt to tie cmt. back to 200' (50' inside of 8 5/8" csg) by pumping 30 sx stages thru 1" int 7/8" x 5 1/2" annulus as required.



18. I hereby certify that the foregoing is true and correct

SIGNED M. Lee

TITLE Drig. & Comp. Engineer

DATE 3/06/91

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 3/13/91

CONDITIONS OF APPROVAL, IF ANY:

\* all changes and/or additions as per telecon w/M. Lee, 3/11/91.

\*See Instructions on Reverse Side

SJS