Form 9-331 (May 1963)

TED STATES SUBMIT IN TRI. JCATE* DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)

4,9		Form a	approv	ed.		
		Budget	Bure	au N	o. 42	-R1424
5.	LEASE	DESIGN	NATION	AND	SERI	AL NO.

GEOLOGICAL S	iU	JR.	V	EΥ
--------------	----	-----	---	----

GEOLOGICAL SURVEY		NM	9987			
RY NOTICES AND REPORTS ON WELLS m for proposals to drill or to deepen or plus back to graduate Design.	6.	IF INDIA	N, ALLOTTE	OR	TRIBE	NAM

	(Do no	ot use this	form Use	for proposals to "APPLICATION	drill or to deepen or pl FOR PERMIT—" for su	ig back to a that Deseroir.
1.	MELL X	GAS WELL		OTHER		AUG 7 = 1987
0	NAME OF C	DEPATOR			/	

O. C. D. Fred Pool Drilling, Inc. ARTESIA, OFFICE

3. ADDRESS OF OPERATOR P.O.Box 1393, Roswell, N.M.88201

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

2310 FSL and 1076 FWL

CLINID

14. PERMIT NO. 30-015-25726

16.

1.8

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

36801

FIELD AND POOL, OR WILDCAT East Red Lake -4-

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

Max Federal 🞏

11. SEC., T., R., M., OR BLK. AND SUBVEY OR AREA

Sec. 30-16S029E 12. COUNTY OR PARISH 13. STATE Eddy N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:					SUBSEQUENT REPORT OF:				
		1	Γ	1					
TEST WATER SHUT-OFF		PULL OR ALTER CASING			WATER SHUT-OFF		REPAIRING WELL		
FRACTURE TREAT		MULTIPLE COMPLETE	ļ		FRACTURE TREATMENT		ALTERING CASING		
SHOOT OR ACIDIZE	ļ	ABANDON*	X		SHOOTING OR ACIDIZING		ABANDONMEST*		
REPAIR WELL		CHANGE PLANS	ļ		(Other)				
(Other)					(Nork: Report res Completion or Reco	ults of mplet:	f multiple completion on We ion Report and Log form.)	:H	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

July 29,1987 Intend to Plug and Abandon this well as follows:

- Spot cement plug from approximately 1900' to 1700', Tag plug.
- 2. Spot cement plug across shoe of surface casing, +220' to 120' and tag plug.
- Spot 50' surface plug.
- No casing will be recovered.
- Regulation dry hole marker will be installed and location cleared and reclaimed.
- 6. Work will commence approximately 8-3-87.

SIGNED Talford The Signed Signed Talford Talfo	TITLE _	Petroleum Engineer	DATE _	7-29-87	
(This space for Federal or State office use) APPROVED BY CLOSE Mann CONDITIONS OF APPROVAL IF ANY:	TITLE	A Leavest State	DATE _	8-4-87	