

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-101
Revised 1-1-88

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

WELL API NO. 30-015-27161
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-11593
7. Lease Name or Unit Agreement Name Diamond A "35" State
8. Well No. 1
9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS JAN 25 1993 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) O.C.D. OTHER CERT F	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Mewbourne Oil Company	
3. Address of Operator P.O. Box 5270 Hobbs, New Mexico 88241	
4. Well Location Unit Letter <u>D</u> : <u>915</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>West</u> Line Section <u>35</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>Eddy</u> County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3682' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
01/12/93
Post ID-2
1-29-93
P4A

T.D. well @ 10,720'. Ran logs and evaluated well. Decided to plug well. Notified NMOCD Office in Artesia, New Mexico and received plugging instructions and verbal approval from Mike Williams. Set 35 sk. Class "H" Neet plugs @ 10,156', 8,141', 6,900', 6,094' and 5,412'.

01/13/93

Continued plugging well. Set 35 sks. Class "H" Neet plug @ 3737'. Set 50 sack Class "H" plug containing 2% CaCl2 @ 2,653'. WOC 3 hrs. and tagged top of plug @ 2,557'. Set 165 sk. Class "H" Neet plug from 465' to surface. Cut off wellhead, welded steel plate of surface casing and installed dry hole marker. Filled in cellar, rat & mouse hole.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bill Pierce TITLE Drilling Supt. DATE 01/20/93
(505)
TYPE OR PRINT NAME Bill Pierce TELEPHONE NO. 393-5905

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY RAY SMITH TITLE OIL AND GAS INSPECTOR DATE DEC 20 1993
CONDITIONS OF APPROVAL, IF ANY: