

The cement bond log run on July 20, 1993, from 8100 feet to 6000 feet, shows that good cement bond is present up to 6000 feet. A copy of the log is attached.

The attached Sundry Notice states that on August 26, 1993, the zone from 6868 feet to 7038 feet was perforated, and then fluid was pumped out of the well. As fluid was pumped between August 26, 1993 and September 5, 1993, the volume of fluid produced decreased from 276 barrels to 27 barrels. The ability to pump down the fluid level in the well demonstrates that the zone at 6868 feet to 7038 feet was isolated by cement from any other zones that might have produced fluid while the well was being pumped.

The cement sheath around the long-string casing of Map ID No. 161 extends above the top of the injection zone. Therefore, this wellbore will not provide a pathway for migration of fluids or transmittal of pressure from the injection zone.

REQUEST 6:

Revise the Closure Plan to state that dry-hole markers will be installed when the wells are plugged.

RESPONSE:

The Closure Plan (Attachment III-5) has been revised as requested. A replacement page is included.