

# New Mexico Operation Center

11/15/1996 To 12/20/1996

<u>Well name</u>	<u>Well no.</u>	<u>FlacHzSub</u>	<u>Kind</u>	<u>Condition</u>	<u>Well status date</u>
EVELYN /35/ STATE COM WELL #1	01	71659701	Gas		12/04/96

<u>Date final'd</u>	<u>Wrk.act.type</u>	<u>Reason</u>	<u>User ID</u>	<u>Fld.est.cost</u>	<u>Wrk.act.no.</u>
12/04/96	Completion		ZTJM18		110

<u>Service unit type</u>	<u>Rig up</u>	<u>Rig dwn.</u>	<u>Capbl.of drlgn?</u>	<u>Service company</u>	<u>Unit no.</u>
Pulling Unit	11/18/96	12/04/96		Gibson	122

<u>Job type</u>	<u>Start dt.</u>	<u>End dt.</u>	<u>FlacHzSub</u>	<u>Highlights</u>
MECH. INTEG. TESTING	11/18/96	11/18/96	71659701	Passed
rih x 4 3/4" bit x tag pbt d at 10755' x displace 5 1/2" n-80 17# casing x 4% filtered kcl fresh water x pressure test casing x 1000 psi x ok x poh.				
LOGGING	11/19/96	11/19/96	71659701	3,300 to 10,744 FT.
cement top was at 3490 feet.				
REMOVED/RUN	11/20/96	11/20/96	71659701	Work Activity
PERFORATION	11/21/96	11/21/96	71659701	10,570 to 10,578 FT.
drop bar x perforate from 10570-10578' x 6 spf x tcp gun x 27" penetration x 21 1/2 gram charge x slight blow.				
TESTING/SWABBING	11/21/96	11/22/96	71659701	10,570 to 10,578 FT.
drop bar x perforate x slight blow x wait 1 hr x tpc 35 x run swab x ifl 6600 fs x swab 3 hr x rec 10 blw x ffl 10300 fs x 14 hr tpc 525 x bled dn x 5 min x run swab x ifl 9000 fs x made 2 runs x swab dry x 200'fluid entry per hour x acidize next day.				
WIRELINE	11/25/96	11/25/96	71659701	Activity: Sliding Sleeve
rih x wl x release tcp perforating guns in order to get coil tbg down to for acid job. when released guns dropped 45 1/2' down hole.				
ACIDIZING	11/25/96	11/25/96	71659701	10,570 to 10,578 FT.
rih x 1.25' coil tbg x disp x n2 to 10610' x acd x 2400 gals 7 .5% x 178000 scf n2 x max prs 4400 x min prs 4300 x shut in x 1.5 hr x flow back x 3 hrs x rec all of 57 blw x no show of gas x poh x coil tbg x shut down overnight.				
TESTING/SWABBING	11/26/96	12/03/96	71659701	10,570 to 10,578 FT.
swab 4 days after acid x n2 job x recovered 36 bfmw x no gas x oil x swab dry each day x shut well in due to waiting for partners ok to move up hole to next zone.				
WIRELINE	12/02/96	12/02/96	71659701	Activity: Bomb
rih x wl pressure b0mbs x stopping 3 minutes at following intervals 2000' x 4000' x 6000' x 8000' x 9000' x 10000' x 10553' at mid point of perforations.				