

WELL TEST INTERPRETA CLIENT : OXY USA INC		REPORT #:150925	PAGE: 12. 12-MAY-97
REGION :CSD DISTRICT:HOBBS BASE :MIDLAND ENGINEER:LARRY DAVIS	DISTRIBUTION OF REPORTS		FIELD: ZONE : WELL :VIKING FED #1 LOCATION:

SCHLUMBERGER has sent copies of this report to the following:

=====

OXY USA INC  
BOX 50250  
MIDLAND . TX 79710  
( 2 copies)

OXY USA INC  
BOX 1387  
CARLSBAD . NM 88231  
Attn: JOHN STINSON  
( 1 copy)

Any interpretations or recommendations are opinions and necessarily based on inferences and empirical factors and assumptions, which are not infallible. Accordingly, Schlumberger (Flopetrol Johnston) cannot and does not warrant the accuracy of correctness of any interpretation or measurement. Under no circumstances should any interpretation or measurement be relied upon as the sole basis for any drilling, completion, well treatment or production decision or any procedure involving risk to the safety of any drilling venture, drilling rig or its crew or any other individual. The Customer has full responsibility for all drilling, completion, well treatment, and production procedure, and all other activities relating to the drilling or production operation.