State of New Mexico Jy, Minerals and Natural Resources Departme

For	m C	-103	3
Re	vised	11-1	1-8

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

WELL API NO.	-	. ——	
30-015-29421			
Indicate Type of Lease			
	s	TATE	FEE

		Santa	re, NIVI O	7 000	L				
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			sIndicate Type of Leas	_		٦			
						1	STATE	FEE	١
DISTRICT III	=				ļ	«State Oil & Gas Leas	e No.	 _	٦
1000 Rio Brazos Rd., Aztec, NM 8	37410								١
CHMDE	SA NULIUE	S AND REPORT	S ON ME	IS	-				3
(DO NOT USE THIS FORM	FOR PROPOS	SALS TO DRILL OR	TO DEEPEN	OR PLUG BACK	ктоа	₁Lease Name or Unit	Agreement Name	oʻrda s alsil	
DIFFEREN	NT RESERVOIF	R. USE "APPLICAT	TION FOR PE	RMIT"			g		
	(FORM C-101)	FOR SUCH PROP	OSALS.)			Sandy Crossing 3	32 State Com		
Type of Well:						'			
OIL GA	AS ÆLL	OTHE	R Dry						
₂Name of Operator						•Well No.		_	
Nearburg Producing Comp	pany			_		1			
sAddress of Operator						•Pool name or Wildca			
3300 North A Street, Build	ling 2, Suite 1.	20, Midland, Texa	s 79705			Logan Draw - M	опом		_
4Well Location			0		000				
Unit Letter! : _	1980 Feel	t From The	South	Line and	990	Feet From The	East	Line	
	22	T	17S	D	27E	NMPM	Eddy	County	
Section	32	Township		Range , RKB, RT, GR, etc.		INMEN	In the second	County	
	n or me man alors were bound	3,475' GR		, MD, KI, GK, 6K	···)				
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data									
NOTICE	OF INTE	NTION TO:			SUBS	SEQUENT RE	PORT OF:		
PERFORM REMEDIAL WORK		PLUG AND ABAND	OON	REMEDIAL WO	ORK		ALTERING CASI	NG [
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE D	RILLING O	PNS.	PLUG AND ANBA	NDONMENT [
PULL OR ALTER CASING				CASING TEST	AND CEME	ENT JOB			

OTHER: Temporarily Abandonment

12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set 35 sx cement plug from 9,335'-9,445'. 1)
- Set 35 sx cement plug from 7,258'-7,368'. 2)
- Set 45 sx cement plug from 6,138'-6,314'. Circ and WOC. TIH & tag cmt at 6,250'. 3)
- Set 45 sx cement plug from 2,924'-3,100'. Circ and WOC. TIH & tag cmt at 3,009'. 4)
- Pump 10 sx cement at surface. 6)
- ND BOPE. Cut off wellhead. 5)
- RDMO drilling rig. T&A'd well. Final report.



I hereby certify that the information above is true and com	plete to the best of my knowledge a	and belief.	-/-/h-
SIGNATURE TO COLL	mulran HILE	Manager of Drilling and Production	DATE 12/19/97
SIGNATURE			
TYPE OR PRINT NAME E. Scott Kimbrough	U		TELEPHONE NO. (915) 686-8235
THE OKTAME E. COST. Through			

(This space for State Use)

OTHER:

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: