

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-85

dist
of

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-015-29421
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name Sandy Crossing 32 State Com
Well No. 1
Pool name or Wildcat Red Lake, Queen, Grayburg, San Andres
Elevation (Show whether DF, RKB, RT, GR, etc.) 3475'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
Name of Operator Nearburg Producing Company
Address of Operator 3300 N A St. Bldg 2, Suite 120, Midland, TX. 79706
Well Location Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>990</u> Feet From The <u>East</u> Line Section <u>32</u> Township <u>17S</u> Range <u>27E</u> NMPM <u>Eddy</u> County
Elevation (Show whether DF, RKB, RT, GR, etc.) 3475'

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug # 1 2-23-01 Set CIBP @ 1750'. Circulate well with mud laden fluid

Plug # 2 2-23-01 Spot 20 sks of C cement @ 1750'. Tag @ 1225'

Plug # 3 2-24-01 Spot 10 sk surface plug @ 30'-surface

2-25-01 Cut off wellhead and anchors 3' BGL Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Asmt. DATE 2-26-01

TYPE OR PRINT NAME JACK SHELTON TELEPHONE NO 915-523-5155

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE JAN 25 2002

CONDITIONS OF APPROVAL, IF ANY: