

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-30166
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-4129
7. Lease Name or Unit Agreement Name	Crow ASM State Com
8. Well No.	1
9. Pool name or Wildcat	POW Morrow
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3621' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter N : 660 Feet From The South Line and 2310 Feet From The West Line Section 32 Township 16S Range 28E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate & acidize <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-1-98 - Cleaned location, set and tested anchors. Moved in and rigged up pulling unit. Nippled up BOP. TIH with bit, scraper and tubing. Tagged PBTD at 9903'. Circulate casing clean with 3% KCL. TOOH with tubing, scraper and bit.
7-2-98 - Rigged up wireline. TIH with logging tools and ran CBL/GR/CCL logs. TOOH with logging tools. Rigged up lubricator. TIH with 4" casing guns and perforated 9696-9701' w/36 .42" holes (6 SPF - Morrow). TOOH with casing guns. Rigged down wireline and lubricator. TIH with packer and tubing. Set packer at 9649'. Nippled down BOP. Nippled up 5K tree. Tested packer and tree. Swabbed. Shut well in.
7-3-6-98 - Swabbed. Acidized perforations 9696-9701' with 700 gallons 7-1/2% HCL acid with ball sealers. Flowed well down. Swabbed. Shut well in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE July 6, 1998

TYPE OR PRINT NAME Rusty Klein

TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Jim W. Groom BSA TITLE District Supervisor DATE 7-16-98

CONDITIONS OF APPROVAL, IF ANY: