Form 3160-5 (November 1994)							FORM APPROVED OMB No 1004-0135 Expires July 31, 194			
						1.5 Lease Senal No.				
SUNDRY NOTICES AND REPORTS ON WELLS						LC048491A				
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.						16. If Indian, Allottee or Tribe Name				
SUBMIT IN TR	NPLICATE - Other inst	tructions	on reverse	side	ADTESIA	7. If Unit o	r CA/Agreement, N	vame and/or No		
☐ Oil Well 🛛 Gas Well 🖵 Other						8. Well Na	me and No.			
2. Name of Operator OXY USA INC. 16696						OXY Duke Federal #1				
3a. Address P.O. BOX 50250 3b. Phone No. (include area code) MIDLAND, TX 79710-0250 915-685-5717						30-015-				
MIDLAND, TX 79710-0250 915-685-5717 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)							1 Poor, or Explorate	VILW MORNOW		
19BO FNL 660 FEL SENE (H) Sec 13 TITS R27E							or Parish, State	4.01.017.00		
						EDDY NM				
	PPROPRIATE BOX(ES)	TO INDIC	ATE NATUR	RE O	F NOTICE, R	EPORT, OF	OTHER DAT	A		
TYPE OF SUBMISSION	TYPE OF ACTION									
Nouce of Intent	Acidize	Deep	en	\Box	Production (Star	(Resume)	Water Shut-O	off		
Subsequent Report	Alter Casing	Fract	ure Treat		Reclamation		U Well Integrity	i.		
Subsequent Report	Casing Repair	~ ` `	Construction		Recomplete		Duher Spi	rd, Set		
Final Abandonment Notice	Change Plans Convert to Injection		and Abandon Back		Temporarily Ab Water Disposal	andon	<u>(55 \$ (</u>	Cement		
determined that the site is ready	inal Abandonment Nouces shal for final inspection.)									
14. I hereby certify that the foregot	ng is true and correct	<u> </u>		<u> </u>			<u> </u>			
Name (Printed/Typed) DAV	ID STEWART		Title		REGULATOR	Y ANALYS	Т			
Signature Vin	Sh		Date			รใจย				
	THIS SPACE	FOR FED	ERAL OR ST	ATE			<u></u>			
Approved by			l Tit	üe		D	ate			
Conditions of approval, if any, are certify that the applicant holds les which would entitle the applicant to	a or equitable title to those ri	pluce does not ghts in the su	warrant or Of abject lease	îic e						
Title 18 U.S.C. Section 1001, may traudulent statements or representa	es it a crime for any person kr tions as to any matter within its	owingly and unsdictior.	willfully to mak	e lo a	ny department or	agency of the	Unied States any f	aise. fictitious cr		

- ...

(Instructions on reverse-

ATTACHMENT 3160-5 OXY USA INC. OXY DUKE FEDERAL #1 SEC 13 T17S R27E EDDY COUNTY, NM

NOTIFIED BLM 5/29/98 OF SPUD. MIRU PETERSON #8, SPUD WELL @ 0125hrs MDT 5/31/98. DRILL 17-1/2" HOLE TD @ 394', 5/31/98, CHC. RIH W/ 13-3/8" 48# H40 CSG & SET @ 394'. M&P 220sx 65/35-C/POZ W/ 5#/sx GILSONITE + .25#/sx CELLOFLAKE FOLLOWED BY 200sx CL C W/ 2% CaCl₂, DISP W/ FW, PLUG DOWN @ 1545hrs MDT 5/31/98, CIRCULATE 156sx CMT TO PIT, WOC 8hrs. NOTIFIED BLM, DON EARLY WITNESSED CEMENT JOB. CUT OFF CASING, WELD ON STARTING HEAD, TEST TO 900#, OK. NU BOP & TEST TO 1200#, OK. RIH & TAG, DRILL OUT & DRILL AHEAD.

DRILL 11" HOLE TO TD @ 1823', 6/3/98, CHC. RIH W/ 8-5/8" 24# CSG & SET @ 1825'. M&P 550sx 65/35/6-C/POZ/GEL + 5#/sx SALT + 5#/sx GILSONITE + .25#/sx CELLOFLAKE FOLLOWED BY 200sx CL C W/ 2% CaCl₂, DISP W/ FW, PLUG DOWN @ 0945hrs MST 6/3/98, CIRCULATE 250sx CMT TO PIT, WOC 8hrs. BLM NOTIFIED BUT DID NOT WITNESS. ND BOP, SET SLIPS & CUT CSG. NUWH, TEST TO 1000#, OK. RU SAFETY TEST & TEST BOP'S, BLIND RAMS, MANIFOLD, SAFETY VALVES & KELLY COCK TO 5000#, OK. TEST ANNULAR PREVENTWER TO 3000#, OK. TEST CSG TO 2500#, OK. RIH & TAG, DO CMT, TEST TO 600#, OK, DRILL AHEAD.

DRILL 7-7/8" HOLE TO TD @ 9782', 6/21/98, CHC. RIH W/ PLATFORM EXPRESS LOGGING TOOL, POOH. RIH W/ 4-1/2" 11.6# N80 CSG & SET @ 9782'. M&P 800sx CL C W/ 11% CSE + .5% FL-25 + .5% FL-52 + 8#/sx GILSONITE FOLLOWED BY 75sx CL C W/ .1% FL-25, DISP W/ FW, PLUG DOWN 6/23/98. BLM NOTIFIED BUT DID NOT WITNESS. ND BOP, SET SLIPS, CUT OFF CSG, NUWH & TEST TO 5000#, OK. REL RIG @ 1630hrs MDT 6/23/98. SI WOCU.