

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-015-30277

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Washington 33 State

8. Well No.
5

9. Pool name or Wildcat
Artesia Queen Grayburg SA

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3675' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator ☒
ARCO Permian

3. Address of Operator
P.O. Box 1089 Eunice, NM 88231

4. Well Location
Unit Letter **C** : **260** Feet From The **N** Line and **2270** Feet From The **W** Line

Section **33** Township **17S** Range **28E** NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3675' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: **Add SA Shallow Sands Perfs** ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 2958' PBD: 2940' PERFS: 2832-2312'

MIRU PU. POH w/rods & pmp. Install & test BOP.
POH w/tbg. RIH w/bit & scraper, tag PBTD @ 2900, POH.
Set RBP on wireline above Lower San Andres perfs @ 2150'.
RIH & perf San Andres Shallow Sands 1407-2048'
Frac San Andres Shallow Sand perfs down csg.
Force close well 1-1/2-2 BPM.
Flow well back & kill w/produced wtr if needed to clean out frac sand & pull RBP.
RIH w/tbg & anchor.
RIH w/rods & pmp. Place well on pmp.

RECEIVED
OCD - ARTESIA
1238

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Administrative Assistant DATE 07/14/99

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use)

APPROVED BY Jim W. Green TITLE District Supervisor DATE 7-19-99

CONDITIONS OF APPROVAL, IF ANY: