State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-59

	OT CONCERNATIO		1
DISTRICT I P.O. Box 1980, Hobbs, NM \$8240	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			30-015-30372 5. Indicate Type of Lesse
•		A5678970	STATE STATE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	★	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERIMITE! VED (FORM C-101) FOR SUCH PROPOSALS.) DOD ARTES IN			7. Lease Name or Unit Agreement Name
1. Type of Well:			OXY Magn: State Com.
AMET AMET X	OTHER DAY	<u> </u>	23596
2. Name of Operator OXY USA Inc	· •	16 69 6	8. Well No.
3. Address of Operator P.O. Box 50	0250 Midland, TX 79	710 0250	9. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710-0250		Undesg. Logan Draw Morrow	
Section 10	10. Elevation (Show whether	3402'	NMPM Eddy County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING CASING TEST AND C			
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
1/4" HOLE TO TD @ 14 ! @ 1498 '. M&P 750sx 6 CaCl ₂ + .25#/sx CELLOF STATIC FREE + .005gps CMT TO PIT, WOC-19hr	98' 10/14/98, CHC, RUN FL 55/35 POZ/C W/ 6% BENTONIT LAKE + 5#/sx GILSONITE FO FP-6L, DISP W/ FW, PLUG D	.UID CALIPER. RI TE + .005% STATIC LLOWED BY 300sx C XXVN @ 0300hrs MDT DID NOT WITNESS.	S MDT 10/12/98. DRILL 12- H W/ 8-5/8" 24# CSG & SET FREE + .005gps FP-6L + 2% C CMT W/ 2% CaCl ₂ + .005% T 10/15/98, CIRCULATE 180sx CUT OFF CSG & WELD ON EST CSG, OK, DRILL AHEAD.
INSTRUCTIONS. RECEIV CL H CMT AT 9284'. PO POOH TO 3243', SPOT & TAG CMT AT 1320', P	VE VERVAL P&A PROCEDURE FR OOH TO 9033', SPOT 45sx CL 40sx CL CL CMT. POOH TO POOH & SPOT 20sx CL C SUR!	OM BRYAN ARRANT H CMT. POOH TO 1554', SPOT 40sx FACE PLUG. NMOC	& LOG, POOH, CIRC, W/O W/ NMOCD. RIH & SPOT 45sx 6012', SPOT 40sx CL C CMT. CL C CMT, POOH, WOC. RIH D WAS NOTIFIED BUT DID NOT , INSTALL DRY HOLE MARKER,
I hereby certify that the information above is true	and complete to the best of my knowledge and	belief.	. ,
SIGNATURE Was State	π	Regulator	v Analyst DATE 1768
TYPEOR FRONT NAME David St	ewart		тејеноме но. 9156855717
(This space for State Use)	w Bum	Distric	1 Sepenison

APTROVED BY --

CONDITIONS OF APPROVAL, IF ANY: