

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB No. 1004-0135  
Expires July 31, 1996

**SUNDRY NOTICES AND REPORTS ON WELLS**

*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well  
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator ☒  
OXY USA INC. 16696

3a. Address P.O. BOX 50250  
MIDLAND, TX 79710-0250

3b. Phone No. (include area code)  
915-685-5717

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660 FNL 660 FWL NWNW(1) Sec 23 T17S R27E

5. Lease Serial No.  
NM 625527A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.  
Oxy Rosenkwalder Federal #1

9. API Well No.  
30-015-30908

10. Field and Pool, or Exploratory Area  
Logan Draw Morrow

11. County or Parish, State  
EDDY NM

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Deepen
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Fracture Treat
	<input type="checkbox"/> Production (Start/Resume)
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Recombine
	<input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Water Disposal
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Well Integrity
	<input checked="" type="checkbox"/> Other Spud, Set Csg & Cmt.

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See other side

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

DAVID STEWART

Title

REGULATORY ANALYST

Signature

*David Stewart*

Date

2/16/00

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office \_\_\_\_\_

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

ATTACHMENT 3160-5  
OXY USA INC.  
OXY ROSENKAVLIER FEDERAL #1  
SEC 23 T17S R27E  
EDDY COUNTY, NM

NOTIFIED BLM 2/5/00 OF SPUD. MIRU FWA-PETERSON #307, SPUD WELL @ 1600hrs MST 2/5/00. DRILL 17-1/2" TO TD @ 409', 2/6/00, PUMP SWEEP. RIH W/ 13-3/8" 48# H40 CSG & SET @ 409'. M&P 165sx 65:35 C/POZ W/ 6% BENTONITE + 2%  $\text{CaCl}_2$  + .25#/sx CELLOFLAKE FOLLOWED BY 200sx CL C W/ 2%  $\text{CaCl}_2$ , DISP W/ FW, PLUG DOWN 2/6/00, CIRC 71sx CMT TO PIT, WOC-6hrs. BLM NOTIFIED & GENE HUNT WITNESSED CMT JOB. CUT OFF CASING, WELD ON STARTING HEAD, TEST TO 500#, OK. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, & HYDRIL TO 500#, OK. TOTAL WOC-18hrs, RIH & TAG, DRILL OUT & DRILL AHEAD 2/7/00.

DRILL 11" HOLE TO TD @ 1822' 2/8/00. RIH W/ 8-5/8" 32# K55 CSG & SET @ 1822'. M&P 460sx 65:35 C/POZ W/ 6% BENTONITE + 2%  $\text{CaCl}_2$  + .25#/sx CELLOFLAKE + 5#/sx GILSONITE FOLLOWED BY 200sx CL C W/ 2%  $\text{CaCl}_2$  DISP /FW, PLUG DOWN @ 1130hrs MST 2/9/00, CIRC 164sx CMT TO PIT, WOC-6hrs. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, CHOKE LINES, CHOKE MANIFOLD AND SAFETY VALVES TO 5000#, OK. TEST HYDRIL TO 3000#, OK. TEST KILL LINE, MUD LINES, & CASING TO 2500#, BLM NOTIFIED OF CEMENT JOB & BOP TEST, DID NOT WITNESS. RIH & TAG, DO CMT, TEST TO 500#, OK, DRILL AHEAD.