

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-30949
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Sadie AUP
8. Well No.	1
9. Pool name or Wildcat	Atoka Morrow, West
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3479' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter H : 1650 Feet From The North Line and 990 Feet From The East Line
Section 35 Township 17S Range 25E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate & acidize <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-11-2000 - Cleaned location, set and tested anchors. Moved in and rigged up pulling unit. Nippled up BOP. Rigged up wireline. TIH with logging tools and ran CBL/GR/CCL log. TOOH with logging tools and rigged down wireline. TIH with bit, scraper and tubing.

4-12-2000 - Pickled tubing with 500 gallons of 15% iron control HCL acid. TOOH with tubing, scraper and bit.

4-13-2000 - Rigged up wireline. TIH with 4" casing guns and perforated 8050-8054' w/30 .42" holes (6 SPF - Strawn). TOOH with casing guns and rigged down wireline. TIH with packer and tubing. Set packer at 7959' and tested to 2000 psi. Nippled down BOP and nippled up tree. Swabbed. Shut well in.

4-14-2000 - Acidized perforations 8050-8054' with 1000 gallons 7-1/2% MSA acid and 1000 scf/bbl N2. Swabbed. Shut well in.

4-15-17-2000 - Swabbed & flow tested. Shut well in.

4-18-2000 - Pumped 50 bbls 2% KCL. Nippled down tree and nippled up BOP. Released packer. TOOH with packer and tubing. Rigged up wireline. TIH with 4" casing guns and perforated

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations Technician DATE May 17, 2000

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Jim W. Klein TITLE SUPERVISOR, DISTRICT II DATE MAY 25 2000

CONDITIONS OF APPROVAL, IF ANY: