

CISR
BP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM
87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-31189
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Veranda 16 State Com
8. Well No. 1
9. Pool name or Wildcat Kennedy Farms Morrow

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

DEVON SFS OPERATING, INC

3. Address of Operator

20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (405) 235-3611

4. Well Location

Unit Letter 0-660 Feet From The South Line and 1980 Feet From The East Line

Section 16 Township 17S Range 26E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3359'

Check Appropriate Box To Indicate Nature Of Notice, Report, Or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Cmt, Perfs ☐

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

3/27/01 RU Baker Atlas TIH w/ logging Tools Ran Cement Bond Log from 8386' to 3300'

4/4/01 PU Arrow 1-X pac, on/off tool w/1.81" "F" profile nipple & 2 7/8" 6.5# L-80 8rd Tub, TIH Set pac at bottom of pac at 8270.98. Perf'd Morrow 8,366' 8,370' 8,389' - 8,393' 4 SPF Total 32 holes (.40 EHD)

4/6/01 Acidized perfs w/1500 gal 7.5% HCL acid *

4/24/01 Swabbed tub dn. Pulled standing valve. Release on-off tool. TOOH w/ tub & on-off tool. SDON

4/25/01 TIH w/on-off tool & 2 7/8 tub. Test Tub & checked all makeup on tub. Circ hole w/POO Fluid. Latched on on-off tool. Ran chart to 1000# for 30 min. Held ok SDON.

4/27/01 Flow & swab well

5/15/01 Run pressure buildup, Analyzing build up data.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Karen Cottom

TITLE ENGINEERING TECHNICIAN

DATE May 23, 2001

TYPE OR PRINT NAME

Karen Cottom

TELEPHONE NO. (405) 235-3611

(This space for State use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

Approved by *BT*

Conditions of approval, if any:

TITLE _____

DATE

JUN 20 2001