Submit 3 Copies to Appropriate District Office	nd 252627282	State of Ne Ainerals and Natu	ew Mexico ral Resources Depa	artment	- C19/1	Form C Revise	:-103 d 1-1 -89
DISTRICT I P.O. Box 1980, Hobbs, NM 88	,	⁽²⁾	TION DIVISI	ION	WELL API NO. 30-015-31285	<i>,</i>	
DISTRICT II P.O. Drawer DD, Artesia, NM 8	RECEIV OCD - AR	ED 55 anta Fe, NI	M 87505		sIndicate Type of Lea	se STATE	FEE
<u>DISTRIÇT III</u> 1000 Rio Brazos Rd., Aztec, N		Thorogo			₅State Oil & Gas Leas		FEE L.J
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					7Lease Name or Unit Agreement Name Staley State		
1Type of Well: OIL WELL	GAS WELL	OTHER					
aName of Operator SDX Resources, Inc.					₃Well No. 2	i	
3Address of Operator PO Box 5061, Midland	I, TX 79704				Pool name or Wildca Red Lake, QN-		
Well Location Unit Letter	890 Fe	et From The South	Line and	1650	Feet From The	East	Line
Section	30	Township 17S	Range	28E	NMPM	Eddy	County
		10Elevation (Show wheth 2625' GR	er DF, RKB, RT, GR, etc.				
11	Check App	ropriate Box to Indicat	e Nature of Noti	ice, Re	port, or Other [Data	_
NOTICE OF INTENTION TO: SUBS					SEQUENT RE	PORT OF:	
		OLIO AND ADAMBOLI	i i i				
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WO	DRK	\bowtie	ALTERING CASI	₩G
PERFORM REMEDIAL WORK TEMPORARILY ABANDON		CHANGE PLANS	COMMENCE D			ALTERING CASII	
				RILLING O	PNS.		
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:		CHANGE PLANS	CASING TEST OTHER:	RILLING O	PNS.	PLUG AND ANBA	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:			CASING TEST OTHER:	RILLING O	PNS.	PLUG AND ANBA	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12Describe Proposed or Comp work) SEE RULE 1103. 2/28/02 - Set 5-1/2" RE spf). 3/1/02 - Acidize w/82 b 3/5/02 - TOH w/RBP. fire. Perf. 2223', 35, 45 3/6/02 - Acidize w/4000 3/8/02 - Frac down 5-1	Heted Operations (# BP @ 3621'. T bbls 15% NEFE TIH w/5-1/2" C , 52, 64, 2308, 0 gal 15% NEF /2" csg w/60,0 og to 2501'. Set	CHANGE PLANS Clearly state all pertinent details, a IH w/4" select fire. Perf. 293 IBP & 115 jts & set @ 362: 37, 39, 49, 63, 65, 82, 89, E. 00 gal Viking 25 + 95,000# 12-1/2" x 2" x 12' RWAC pi	CASING TEST OTHER: ord give pertinent dates, if 34', 36, 38, 40, 56, 5 1'. TIH w/5-1/2" RBF 95, 2400, 19, 21, 2 16/30, 35,000# 12	AND CEMI Including es 58, 60, 69 P & 89 jts 23, 34, 41	PNS	PLUG AND ANBA	holes, 1
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12Describe Proposed or Compwork) SEE RULE 1103. 2/28/02 - Set 5-1/2" RE spf). 3/1/02 - Acidize w/82 b 3/5/02 - TOH w/RBP. fire. Perf: 2223', 35, 45 3/6/02 - Acidize w/4000 3/8/02 - Frac down 5-1 3/10/02 - Run 2-7/8" tb 3/21/02 - Ran 24 hr tes	Heted Operations (In the SP @ 3621'. To see the St. 16 BO, 18 In the St.	CHANGE PLANS Clearly state all pertinent details, a IH w/4" select fire. Perf. 293 IBP & 115 jts & set @ 362 37, 39, 49, 63, 65, 82, 89, IE. 00 gal Viking 25 + 95,000# 12-1/2" x 2" x 12' RWAC pi MCF, 186 BW	CASING TEST OTHER: OTHER: 34', 36, 38, 40, 56, 5 1'. TIH w/5-1/2" RBF 95, 2400, 19, 21, 2 16/30, 35,000# 12 mp. Begin pmp.	Parady AND CEMI Including es 58, 60, 69 Parady 23, 34, 41	PNS	any proposed 3009, 18, 24 (15	holes, 1 w/4" select 1 spf).
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12Describe Proposed or Compwork) SEE RULE 1103. 2/28/02 - Set 5-1/2" RE spf). 3/1/02 - Acidize w/82 b 3/5/02 - TOH w/RBP. fire. Perf: 2223', 35, 45 3/6/02 - Acidize w/4000 3/8/02 - Frac down 5-1 3/10/02 - Run 2-7/8" tb 3/21/02 - Ran 24 hr tes	leted Operations (in the state of the state	CHANGE PLANS Clearly state all pertinent details, a IH w/4" select fire. Perf: 293 IBP & 115 jts & set @ 362; 37, 39, 49, 63, 65, 82, 89, E. 00 gal Viking 25 + 95,000# t 2-1/2" x 2" x 12' RWAC pr MCF, 186 BW	CASING TEST OTHER: 34', 36, 38, 40, 56, 5 1'. TIH w/5-1/2" RBF 95, 2400, 19, 21, 2 16/30, 35,000# 12 mp. Begin pmp.	Parady AND CEMI Including es 58, 60, 69 Parady 23, 34, 41	PNS	PLUG AND ANBAI any proposed 3009, 18, 24 (15 till in hole). TIH v 7, 72 (26 holes,	holes, 1 w/4" select 1 spf).
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12Describe Proposed or Compwork) SEE RULE 1103. 2/28/02 - Set 5-1/2" RE spf). 3/1/02 - Acidize w/82 b 3/5/02 - TOH w/RBP. fire. Perf: 2223', 35, 45 3/6/02 - Acidize w/4000 3/8/02 - Frac down 5-1 3/10/02 - Run 2-7/8" tb 3/21/02 - Ran 24 hr tes	leted Operations (in the state of the state	CHANGE PLANS Clearly state all pertinent details, a IH w/4" select fire. Perf. 293 IBP & 115 jts & set @ 362 37, 39, 49, 63, 65, 82, 89, E. 00 gal Viking 25 + 95,000# 12-1/2" x 2" x 12' RWAC pi	CASING TEST OTHER: OTHER: 34', 36, 38, 40, 56, 5 1'. TIH w/5-1/2" RBF 95, 2400, 19, 21, 2 16/30, 35,000# 12 16/30, Begin pmp. knowledge and belief. TITLE Regulator	P& 89 jts: 3, 34, 41	PNS	PLUG AND ANBAG any proposed 3009, 18, 24 (15 till in hole). TIH v 7, 72 (26 holes,	holes, 1 w/4" select 1 spf).
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12Describe Proposed or Compwork) SEE RULE 1103. 2/28/02 - Set 5-1/2" RE spf). 3/1/02 - Acidize w/82 b 3/5/02 - TOH w/RBP. fire. Perf. 2223', 35, 45 3/6/02 - Acidize w/4000 3/8/02 - Frac down 5-1 3/10/02 - Run 2-7/8" tb 3/21/02 - Ran 24 hr tes	leted Operations (in the state of the state	CHANGE PLANS Clearly state all pertinent details, a IH w/4" select fire. Perf. 293 IBP & 115 jts & set @ 362 37, 39, 49, 63, 65, 82, 89, E. 00 gal Viking 25 + 95,000# 12-1/2" x 2" x 12' RWAC pi	CASING TEST OTHER: OTHER: 34', 36, 38, 40, 56, 5 1'. TIH w/5-1/2" RBF 95, 2400, 19, 21, 2 16/30, 35,000# 12/mp. Begin pmp.	P& 89 jts: 3, 34, 41	PNS	PLUG AND ANBAG any proposed 3009, 18, 24 (15 till in hole). TIH v 7, 72 (26 holes,	holes, 1 w/4" select 1 spf).



