1_	State of New 1	Aarico	cisi	7
Submit 3 Copies to Appropriate District Office	Energy, Minerals and Natural		$\mathcal{G}_{\mathcal{A}}$	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobby, NM 88240	OIL CONSERVATI	ON DIVISION 088	WELL API NO 30-015-32	2216
DISTRICT II P.O. Drawer DD, Ariesia, NM 88210	Santa Fe, New Mexic	o 87504-2088	5. Indicate Type of	
DISTRICT III 1000 Rio Brizos Rd., Aziec, NM 87410		A	6. State Oil & Gu 1 V-3138	ezse No.
(DO NOT USE THIS FORM FOR PRO	ICES AND REPORTS ON W DPOSALS TO DRILL OR TO DEEP RYOR, USE "APPLICATION FOR F -101) FOR SUCH PROPOSALS.	EN CHAPTER TOURS ON A COLUMN STEEL	7. Lease Name or U	nit Agreement Name
1. Type of Well: Off. OAS WELL X	OTHEEK	1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5	YOGI BEAI	R STATE COM
2. Name of Operator	TNC	2511101	8. Well No.	#1
MURCHISON OIL & GAS, 3. Address of Operator	ING.		9. Pool name or Wi	
1100 MIRA VISTA BLVD	. PLANO, TX. 7509	3-4698	EMPIRE MO	ORROW SOUTH
4. Well Location Unit Letter H : 175	O Feet From The NORTH	Line and 60	60 Foot From	The <u>EAST</u> Line
1.2	170			DDY County
Section 12	Township 1/5 10. Elevation (Show when			
11. Check	Appropriate Box to Indicat	e Nature of Notice, R	eport, or Other	Data
NOTICE OF IN		SUB	SEQUENT RE	EPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	GOPNS. X	PLUG AND ABANDONMENT L
PULL OR ALTER CASING		CASING TEST AND CE	X BOL THAME	
OTHER:		OTHER:		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed				
work) SEE RULE 1103.				
Spud well @ 1:00 PM 5/19/02. Drill 17-1/2" hole to 260'. Ran 7 jts. of 13-3/8" 61 #/FT K-55 Buttress thread casing to 260'. Cemented with 285 SXS Class "C" + 2% S1 + .125 PPS D130 followed by 100 SXS 10/2 RFC (Class "A") + 6# SX D24. Did not circulate. TOC @ 13'. Circulate cement down the backside w/ 75 SX Class "C" neat + 2% S1. Cut off csg. and weld on casing head, test to 1000 PSI. OK. Nipple up 5000 PSI BOP. Test to 6000 PSI. OK. Pick up BOP and trip in hole. WOC total of 23 HRS. Drill out plug and float and resume drilling w/ 12-1/4" hole.				
I hereby certify that the information above by the support of the	we professional to the feet of my boowledge	e and balia.	ENT OPERATIO	
TYPE ON PROTT NAME MICHAEL	S. DAUGHERTY			(972) Telephone No.931–0700
(This space for State Use)	ORIGINAL SIGNEI DISTRICT II SUPE	RVISOR	а	JUL 0 8 2002
CONDITIONS OF APPROVAL, IF ANY:		TITLE .	•	•