Submit 3 Copies To Appropriate District Office	State of New Mexico				Form C	
District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88240 District II				Revised March 25, 1999 WELL API NO. 30-015-32445		
District III 1220 South St. Francis Dr.				5. Indicate Type of Lease STATE FEE		
District IV 1220 S. St. Francis Dr., Santa Fe, MM 87505 BECE				6. State Oil & Gas Lease No. FEE LEASE		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name or Unit Agreement Name:		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:				SKIP AWAY		
Oil Well Gas Well Other 2. Name of Operator /				0.111.11		
MURCHISON OIL & GAS, INC.				8. Well No.	1	
3. Address of Operator 1100 MIRA VISTA BLVD. PLANO, TX. 75093-4698				9. Pool name or UNDESIGNATEI MORROW	Wildcat D KENNEDY FARM	S
4. Well Location	1276 foot from the	COUTI	T 1' 1	1180 0.10	1	
	<u>1376</u> feet from the				m the <u>WEST</u>	_line
10. Elevation (Show whether DR, RKB, RT, GR, etc.)						
11. Check Appropriate Box to Indicate Nature of Notice, Report or NOTICE OF INTENTION TO: SUBSEQUEN						
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR		ALTERING CASIN	G 🗌
	CHANGE PLANS		COMMENCE DRI		PLUG AND ABANDONMENT	
	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	ND 🖾		
OTHER:			OTHER:	·		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.						
Spud well @ 7:30 11/10/02 and drill 17-1/2" hole to a depth of 412'. Run 13-3/8" casing as follows: Texas Pattern Shoe 1'						
	-3/8" 68 #/FT K-55 B oat Insert	UTT		45' 1'		
	-3/8" 68 #/FT K-55 B	UTT	designed the second	<u>72'</u>		,
419' Casing set @ 412'. Pump 540 SXS Class "C" + 2% CaCl + .25% Celloflake. Circulate 150 SXS to reserve pit. Plug down @ 2 AM 11/11/02. Bump plug and float held. WOC. Weld on wellhead and test to 750 PSI. Test OK. Nipple up BOP and test to 600 PSI. Test OK. Pick up BHA and TIH. WOC total of 20 Hrs. Drill plug and float. Test Csg. to 600 PSI. Resume drilling 12-1/4" hole.						
I hereby certify that the information ab	ove is true and complete	to the bes	st of my knowledge	and belief.		
SIGNATURE	averely T	ITLE <u> </u>	VICE PRESIDENT	Γ OPERATIONS		
	L S. DAUGHERTY				Telephone No. 93	
(This space for State use)/// Jim W. Grante Oistict Supervisor NOV 19 2000						
APPPROVED BY 🐱 Conditions of approval, if any:	war in Ma	TTLE	,		DATE	