

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Artesia, NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR

Kincaid & Watson Drilling Company ✓

3. ADDRESS OF OPERATOR

P.O. Box 498, Artesia, New Mexico 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980'/North line, 660'/East line

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

(other) Change plans

5. LEASE

NM 013814

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

RECEIVED

8. FARM OR LEASE NAME

Wright Federal DEC 3 1982

9. WELL NO. 4

O. C. D.

10. FIELD OR WILDCAT NAME ARTESIA, OFFICE

Square Lake Premier

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
1-17-29

12. COUNTY OR PARISH 13. STATE

Eddy New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

Ground level 3685'

(NOTE: Report results of multiple completion or zone change on Form 9-331-C)

RECEIVED

DEC 1 1982

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give completion dates, including estimated date of starting any proposed work. If well is directionally drilled, give wellbore locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

OIL & GAS  
MINERALS MGMT. SERVICE  
ROSWELL, NEW MEXICO

We have permission to plug this well. When we started work on it we had a hole full of oil. We propose to set a pump and pump this well for a short time to see what we have. If it does not produce commercially we will then plug it.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED James A. Gillham TITLE Secretary-Treasurer DATE November 30, 1982

APPROVED

(This space for Federal or State office use)

APPROVED BY: (Civ. Serv.) PETER W. GILHAM TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY

DEC 2 1982

FOR

JAMES A. GILLHAM

DISTRICT SUPERVISOR

\*See Instructions on Reverse Side



UNITED STATES NM OIL CONS. COMMISSION  
DEPARTMENT OF THE INTERIOR DD  
GEOLOGICAL SURVEY Artesia, NM 88210

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☐ well other ☒ Injection well
2. NAME OF OPERATOR  
Kincaid & Watson Drilling Company ✓
3. ADDRESS OF OPERATOR  
P.O. Box 498, Artesia, New Mexico 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1980/North line, 660'/East line  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO:                      | SUBSEQUENT REPORT OF:    |
|---|--------------------------|
| TEST WATER SHUT-OFF <input type="checkbox"/>  | <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/>       | <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/>     | <input type="checkbox"/> |
| REPAIR WELL <input type="checkbox"/>          | <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE <input type="checkbox"/>    | <input type="checkbox"/> |
| CHANGE ZONES <input type="checkbox"/>         | <input type="checkbox"/> |
| ABANDON* <input checked="" type="checkbox"/>  | <input type="checkbox"/> |
| (other) _____                                 |                          |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

We will plug this well as follows:

See attached diagram.

5. LEASE  
NM 01381
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
Wright Federal
7. UNIT AGREEMENT NAME  
Square Lake
8. FARM OR LEASE NAME  
Wright Federal
9. WELL NO.  
4
10. FIELD OR WILDCAT NAME  
Square Lake
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
1-17-29
12. COUNTY OR PARISH  
Eddy
13. STATE  
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
Ground level 3685'

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

**RECEIVED**  
NOV 12 1982

OIL & GAS  
MINERALS MGMT. SERVICE  
ROSWELL, NEW MEXICO

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Secretary-Treasurer DATE November 10, 1982

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

**APPROVED**

NOV 23 1982

[Signature]  
JAMES A. GILLHAM  
DISTRICT SUPERVISOR

OPERATOR: Marion Watson - Mex. Co., Uresca, N.M.


WELL: 4 - Wright LEASE NO.: 712013814

LOCATION: 1980/N + 660/E sec 1 - T. 17S, - R. 29E.

Min. requirements needed for  
plugging program

Peter W. Chester

7/27/82



(5) 20sx surface plug  
(at least 50' to surface)

(4) 100' cement plug  
597' - 497'

top of salt 525'

(3) If 4 1/2" casing cut & pulled Base of salt 970'  
place 100' cement plug in open  
hole 1070' - 970'.

If 4 1/2" casing not pulled, perf 4 1/2" casing at  
1070' and pump cement behind 4 1/2" casing to  
tie back into 8 5/8" casing at least 100'.  
Leave 100' cement plug in 4 1/2" casing (1070' - 970').

(2) If 4 1/2" casing is to be cut & pulled  
there will be a cement plug across  
the stub from 50' below to  
50' above.

Queen 1995'

ft. 2674' - 2741'  
768'  
~~090'~~

Perft. 2579' - 2589'

(1) Isolate perfs by;  
(a) Cement plug from

Premier 2707'

San Andres 2740'

→ T.D. to 2530' Plug will be tagged.

or (b) C.I.B.P. at 2530'

capped with 35' cement w/ dump trailer  
or 25sx if thru tubing.

35 socks