	,- N.I	I.O.C.D. COPY	U->F
Form 9-331 (May 1963)	UN., ED ST	ATES SUBMIT IN	TRIPLACTE. Form approved. Budget Bureau No. 42-R1424.
		HE INTERIOR (Other inst verse side)	5. LEASE DESIGNATION AND SERIAL NO.
	GEOLOGICAL	SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not	SUNDRY NOTICES AND nee this form for proposals to drill or to Use "APPLICATION FOR PER!	REPORTS REPORTS	ED
	Use "APPLICATION FOR PER	(IT for such proposals.)	MAY - 8 1980
1. OIL WELL	CAS WELL OTHER Juy, We RATOR	el _ APR 251	980 7. UNIT AGREEMENT NAME O. C. D
2. NAME OF OPE		II. S. GEDLUGICAL	SURVEY 8. FARM OF LEASE NAME ARTESIA, OFFICE Featherstone A
3. ADDRESS OF C	aRue and B. N. Muncy, Jr	ARTESIA, NEW	MEXICO 9. WELL NO.
•••			
<u>P. O. B</u>	ox 196 Artesia, N. M WELL (Report location clearly and in acc	.* 10. FIELD AND POOL, OR WILDCAT	
4. LOCATION OF See also space At surface	e 17 below.)	Square Lake (G, SA)	
6601 FN	L and 1980' FEL Section	11. SEC., T., B., M., OR BLK. AND SUBVEY OR ARTA	
000 PN	L and 1900 The Decelon	, ,	SULVEI UR ALEA
		175	Section 1, T17S, R29E
14. PERMIT NO.	15. ELEVATIONS	(Show whether DF, RT, GR, etc.)	12. COUNTY OB PARISH 13. STATE
			Eddy N. M.
16.	Check Appropriate Box	To Indicate Nature of Notice	e, Report, or Other Data
NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:
TEST WATER	SHUT-OFF PULL OR ALTER C.	SING WATER SHU	CT-OFF REPAIRING WELL
FRACTURE TH	MULTIPLE COMPLI	TE FRACTURE 2	TREATMENT ALTERING CASING
SHOOT OR AC	PIDIZE ABANDON*	SHOOTING (	OR ACIDIZING ABANDONMENT* X
REPAIR WELL	CHANGE PLANS	(Other)	
(Other)		(Noti Comp	<b>c</b> : Report results of multiple completion on Well detion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Plugged well by setting bridge plug above perforations with 10 sacks cement on top of bridge plug. Oil string shot off at 1740'. Pumped 30 sacks cement at casing cut off point, 30 sacks cement at 900'-1,000' at base of salt, 20sacks cement at base of surface pipe, 10 sacks cement at surface, with heavy mud between all plugs. Dry hole marker set, and location cleaned.

18. I hereby certify that the foregoing is true and correct SIGNED	TITLE Operator	DATE 4/23/80
(This space for Federal or State office use) (Orig. Sgd.) GEORGE H. STEWART APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	ACTING DISTRICT ENGINEER	DATE MAY 0 7 1330