

0. COPIES RECEIVED	2
DISTRIBUTION	
NTA FE	
LE	✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	21

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

AUG 13 1974

O. C. C.

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	B-7597

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator C. O. Fulton ✓	8. Farm or Lease Name State C
3. Address of Operator P.O. Box 1121 Artesia, New Mexico 88210	9. Well No. 1
4. Location of Well UNIT LETTER <u>H</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>17 S</u> RANGE <u>29 E</u> NMPM.	10. Field and Pool, or Wildcat Square Lake
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug this well as follows:

Spot 25 sk cement plug across perforation.
Spot 35 sk cement plug in and out of stub of 4 1/2".
Spot 35 sk cement plug in shoe joint of 8 5/8" casing.
Set regulation marker with 10 sk cement plug at surface.
Heavy mud will be pumped between all plugs.
Will clean location & back-fill all pits.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. O. Fulton TITLE Owner DATE 8-13-74

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE AUG 14 1974

CONDITIONS OF APPROVAL, IF ANY: Spot a 25 sack plug at top of Queen @ 1920 by 4 1/2" comes below this point. Spot a 25 sack plug @ top of salt @ 925