

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**RECEIVED**  
**JUN 14 1976**  
**O.C.C.**  
**ARTESIA, OFFICE**

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-7071</b>
7. Unit Agreement Name <b>CAVE POOL UNIT</b>
8. Farm or Lease Name <b>CAVE POOL</b>
9. Well No. <b>13</b>
10. Field and Pool, or Wildcat <b>CAVE</b>
12. County <b>Eddy</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CLEAN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <b>Injection</b>
2. Name of Operator <b>JEM Resources Inc.</b>
3. Address of Operator <b>B ox 648 Artesia, N. Mex. 88210</b>
4. Location of Well UNIT LETTER <b>F</b> <b>1980</b> FEET FROM THE <b>W</b> LINE AND <b>1980</b> FEET FROM THE <b>N</b> LINE, SECTION <b>4</b> TOWNSHIP <b>17</b> RANGE <b>29</b> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) <b>3595 GR</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

8 5/8 set at 256 & Circulated. 5 1/2 set at 2410 with 100 sacks. Top perf 2376

Set 20 sacks at 2316 & tagged plug at 2096. Shot pipe at 1550 & pulled out. Set 35 sacks at 1500 & 35 sacks at 650 & 35 sacks at 270 & lost it. Ran 5 sacks hulls & 10 sacks cement at 300 & tagged plug at 270. Set 35 sacks at 270 & tagged at 253. Set 10 sacks & tagged at 209. Set 10 sacks & Marker at top.

Hole was Loaded with mud laden fluid. Cement was Portland type 2,

*R & A 6-10-76*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Paul S. Lee* TITLE *PRF* DATE *6-14-76*

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: