

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

RECEIVED
 NEW MEXICO OIL CONSERVATION COMMISSION
JUN 14 1976
O. C. C.
ARTESIA, OFFICE

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-55

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-7071
7. Well Agreement Name CAVE POOL UNIT
8. Form of Lease Name CAVE POOL
9. Well No. 13
10. Field and Pool, or Wildcat CAVE
12. County Eddy

SUMMARY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR A WELL TO BE DRILLED OR TO DEEPEN OR PLUG, OR TO A DIFFERENT RESERVOIR.
 USE FORM C-101 FOR PERMIT OR FROM C-1011 FOR NOT REPRODUCIBLE

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Injection
2. Name of Operator J&M Resources Inc.
3. Address of Operator Box 648 Artesia, N. Mex. 88210
4. Location of Well UNIT LETTER F 1980 FEET FROM THE W LINE AND 1980 FEET FROM THE N LINE, SECTION 4 TOWNSHIP 17 RANGE 29 N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 3595 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8 5/8 set at 256 & Circulated. 5 1/2 set at 2410 with 100 sacks. Top perf 2376

Set 20 sacks at 2316 & tagged plug at 2096. Shot pipe at 1550 & pulled out. Set 35 sacks at 1500 & 35 sacks at 650 & 35 sacks at 270 & lost it. Ran 5 sacks hulls & 10 sacks cement at 300 & tagged plug at 270. Set 35 sacks at 270 & tagged at 253. Set 10 sacks & tagged at 209. Set 10 sacks & Marker at top.

Hole was Loaded with mud laden fluid. Cement was Portland type 2,
RA 6-10-76

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>B.W. Weaver</i>	TITLE PRES	DATE 6-14-76
APPROVED BY B.W. Weaver	TITLE OIL AND GAS INSPECTOR	DATE 8-12-78

CONDITIONS OF APPROVAL, IF ANY: