

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-015-02905

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-7594

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Arapahoe Oil & Gas

3. Address of Operator

P.O. Box 1517, Roswell, NM 88202-1517

4. Well Location

Unit Letter I : 1980 Feet From The SOUTH Line and 660 Feet From The EAST Line

Section

5

Township

17S

Range

29E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3616' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: Work performed to determine presence of ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See Attached

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Tommy Folsom

TITLE

Consultant

DATE

5-27-93

TYPE OR PRINT NAME

Tommy Folsom

TELEPHONE NO.

(This space for State Use)

APPROVED BY

TITLE

DATE

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-02905
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B7596

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ GAS WELL ☐ OTHER ☐	7. Lease Name or Unit Agreement Name Cave Pool UNIT
2. Name of Operator Arapaho Oil & Gas	8. Well No. 21
3. Address of Operator P.O. Box 1517, Roswell, NM 88202-1517	9. Pool name or Wildcat Cave
4. Well Location Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line Section 5 Township 17S Range 29E NMPM Eddy County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3416' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. TIM W/OE Tbg + SPOT 25 SX Plug AT TOP OF CSG COLLAPSE + Pressure To 100# To squeeze CSG collapse Tag Plug
2. Circulate hole w/10# salt gel
3. Perf squeeze holes @ 1700' SPOT 25 SX CMT Plug + squeeze To 200#
4. SPOT 25 SX Plug @ 1,140'
5. SPOT 25 SX Plug @ 800' across 7 5/8" shoe 800' to 600' to hole
6. Perf holes @ 500' + attempt to circulate between 1/2" + 7 5/8" CSG (Tag Plug)
7. Set 10 SX surface plug
8. Cut off well head, erect P+A marker w/ ALL PERTINENT INFORMATION
Cut off dead man + Clean location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Timmy Folsom TITLE CONSULTANT DATE 5-27-93
TYPE OR PRINT NAME Timmy Folsom TELEPHONE NO. _____

(This space for State Use)

APPROVED BY Mark Behling TITLE Asst DATE 5-28-93

ARAPAHO OIL & GAS
DAILY WELL REPORT

Lease CPU AFE Verable Date 5-22-93 Day 1 FETD
Well# 1 Contractor TR Well Service Rig# 1 Down Time
Csg Size, Wt & Shoe Depth 4 1/2" 9.5" C 2445
Packer or Anchor Type, Depth & shear _____
Tbg Size 2 3/8 Rods 5/8 _____ Perfs _____ to _____
Tbg Grd & Wt J-55 4.7" Rods 3/4 _____ to _____
S.N. Depth _____ Rods 7/8 _____ Squeezed Perfs _____
EOT _____ Rods 1 _____ to _____
Pump Description _____
Unit Size _____ Stroke Length _____ SPM _____


HRS	Brief description of Operation
3	RDPV (Drove Rig To Location 5-21-93)
3	TIH W/ 3 3/4" Lead Impression Block Tallied in Hole W/ 64 JTS Tbg + Tagged at 2018'. Jarred down To Mark Impression Block + Fell Through To open hole. Picked up three JTS Tbg + Tagged @ 2081' Jarred down in soft fill, pulled up to 18 points to become free
2	POOH + Laid down Tbg Impression Block was sheared on one side indicating point entering open Hole
4	RU Computalog Ran CBL From 1900' To Top of fluid @ 200' Bottom of CMT indicated at 1580' + Top of CMT @ 24'
2	RDPV + Released all Equipment

Arapaho Oil + g s
CPU #21

1980' FSL + 660' FEL

Sec. 5, T-17S, R-29E

Spudded 3-14-57



7 7/8" 24# H40 @ 710' CMT Circ
8 Centralizers used

hole in casing @ 1,540' squeezed +
repaired 4/1957 Bottom of CMT 1,580'
Top of CMT 624' By CBL

open hole drilled outside csg 2018' to 2030'

Perforations 2370' to 2388' Premier

4 1/2" 9.5# H40 @ 2470'

CMT w/50 SKS neat CMT

TOC by Temperature survey 1,755'

3-24-57 16 Centralizers +

50 scratchers used

Arapaho Oil & Gas
 CPU 21
 1980' FSL + 640' FEL
 Sec 5, T-17S-R-29E
 Eddy County, New Mexico

