DISTRIBUTION SANTA FE FILE	NEW MEXICO OIL CONSERVATION COMMISSION	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65
U.S.G.S.	OCT 5 1976	Sa. Indicate Type of Lease
OPERATOR /	8.6.6	State OH 6 Gas Lease No.
	O. C. C.	E-741
SUNDRY NO STREET FOR THE STREET AND STREET A	OTICES AND REPORTS ON WELLS	
ore CAS Wree CAS Wree CAS	ormer. Injection	CAVE POOL UNIT
JEM Resources Inc	· · ·	6. Farm of Lease Name CAVE POOL Ut
3. Adimen dispender B ox 648 Artesia	, N. Mex. 88210	2. Vett No. 1 38
4. Location of Well UNIT CETTER	NLINE AND660FEET	10. Field and Pool, or Wildcat CAVE - GRBG
	8 TOWNSHIP 17 RANGE 29	WARMEN.
	15. Elevation (Show whether DF, RT, GR, etc.) 3641 DF	12. County Eddy
PULL OR ALTER CASING OTHER	PLUG AND ABANDON REMEDIAL WORK COMMENCE ORILLING OPHS. CHANGE PLANS CASING TEST AND COMENT JOB OTHER	PLUG AND ABANDONMENT
	ons (Clearly state all pertinent details, and give pertinent dates, incl.	
8 5/8 set at 1670. Base of ,salt	321. 5 1/2 set at 2425. Top perf 2 t 655.	353. Top of Queen
Seti20 sacks	at 2300 & tagged at 2130. Shot pip	e at 1800 & mulled
		o wo lood w puritue
	stub plug & 35 sacks at 1720. 35 sacks	
out. Set 35 sacks	•	acks at 700 &
out. Set 35 sacks 35 sacks at 370.	stub plug & 35 sacks at 1720. 35 sacks at 1720. 35 sacks additional formula of the sacks at 1720.	acks at 700 &
out. Set 35 sacks 35 sacks at 370. 3 250. Set 10 sacks	Tagged at 314 & set 15 sacks addition	acks at 700 & onal. Tagged at
out. Set 35 sacks 35 sacks at 370. 3 250. Set 10 sacks	Tagged at 314 & set 15 sacks addition & Marker at top.	acks at 700 & onal. Tagged at
out. Set 35 sacks 35 sacks at 370. 3 250. Set 10 sacks	Tagged at 314 & set 15 sacks addition & Marker at top.	acks at 700 & onal. Tagged at

Pres.

OIL AND GAS INSPECTOR

AUG - 8 1978