

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION

MAY 26 1976

**O. C. C.
ARTESIA, OFFICE**

Form C-103
Supersedes C-101
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Free <input type="checkbox"/>
5. State Oil & Gas Lease No.	E 4200

SUNDRY NOTICES AND REPORTS ON WELLS

DON NOT USE THIS FORM FOR THE PURPOSES OF WELL OIL OR GAS OR TECH. DATA TO A DIFFERENT RESERVOIR.
ONLY APPLICATION FOR REPORT ON WELLS (FORM C-103) FOR SUCH PURPOSES.

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: In jection
2. Name of Operator JEM Resources Inc.
3. Address of Operator Box 643 Artesia N. Mex. 88210
4. Location of Well UNIT LETTER I 2310 FEET FROM THE S LINE AND 660 FEET FROM THE E LINE, SECTION 9 TOWNSHIP 17 RANGE 29 N.M.P.M.

7. Unit Agreement Name Cave Pool Unit
8. Farm or Lease Name Cave Pool
9. Well No. 46
10. Field and Pool, or Wildcat Cave
12. County Eddy

15. Elevation (Show whether DF, RT, GR, etc.)

3600 DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7 5/8 Surface set at 710' & Circulated. 4 1/2 Casing set at 2480' in 6 3/4 hole. Top of cement at 1710. Top perf. 2430

Set CIBP & 3 sacks at 2380, shot pipe at 1695 & set 35 sacks stub plug & covered Queen. Set 35 sacks at shoe of Surface & 10 sacks & Marker at top.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE **Pres.** DATE **5/24/76**

APPROVED BY *[Signature]* TITLE **OIL AND GAS INSPECTOR** DATE **JUN 01 1976**

CONDITIONS OF APPROVAL, IF ANY: