

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED NEW MEXICO OIL CONSERVATION COMMISSION

OCT 5 1976

O. C. C.

ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State ☒ Fee ☐
5. State Oil & Gas Lease No.	E-950

SUNDY NOTICES AND REPORTS ON WELLS

1. OIL WELL ☐ GAS WELL ☐ OTHER: Injection	7. Unit Agreement Name CAVE POOL UNIT
2. Name of Operator JEM Resources Inc.	8. Farm or Lease Name CAVE POOL <i>ut</i>
3. Address of Operator Box 648 Artesia, N. Mex. 88201	9. Well No. 34
4. Location of Well UNIT LETTER D 330 FEET FROM THE W LINE AND 330 FEET FROM THE N LINE, SECTION 9 TOWNSHIP 17 RANGE 29 NMPM.	10. Field and Pool, or Wildcat CAVE-GRBG
15. Elevation (Show whether DF, RT, GR, etc.) 3597 DF	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	
OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8 5/8 surface set at 256 with 100 sacks. 7" set at 2370 with 200 sacks.
Base of salt 655 Top of Queen 1663. Open hole from 2370 to 2417.
Will set 25 sacks at 2320⁷⁰ & tag plug. Shoot pipe & pull out. If
Queen is open will set 35 sacks 1713-1613. Set 35 sacks 705-605 &
35 sacks 300-200. 10 sacks & Marker at top.
Cement will be Portland type 2. Hole will be loaded with Mud Laden
Fluid.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Wally Bell* TITLE Pres. DATE 10-5-76

APPROVED BY *W.A. Gressett* TITLE SUPERVISOR, DISTRICT II DATE OCT 6 1976

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

Plugging