

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

AUG 9 1976

Form C-103  
Supersedes Oll  
C-102 and C-101  
Effective 1-1-65

O. C. C.  
ARTESIA, OFFICE

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	E-950

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR RE-DRILL OR RE-ENTER A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT - FORM C-101 FOR SUCH PROPOSAL)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input checked="" type="checkbox"/> Injection	7. Unit Agreement Name Cave Pool Unit
2. Name of Operator Jem Resources Inc.	8. Form or Lease Name Cave Pool Unit
3. Address of Operator Box 648, Artesia, N.Mex. 88210	9. Well No. 45
4. Location of Well UNIT LETTER H 1980 FEET FROM THE N LINE AND 660 FEET FROM THE E LINE, SECTION 9 TOWNSHIP 17 RANGE 29 NMPM.	10. Field and Pool, or Wildcat Cave
11. Elevation (Show whether DF, RT, GR, etc.) GR 3572	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10 3/4" Surface set at 353 and circulated. 7" casing set at 2443 with 100 sacks. Top perf at 2420. Top of queen 1710. Base of salt at 710.

Will set 25 sacks at 2370 and shoot pipe and set 35 sacks stub plug. If Queen is open will set 35 sacks at 1760- 1660. Set 35 sacks 760 -660 and 35 sacks 400 - 300 and 10 sacks and marker at top.

Hole will be loaded with MLF. Cement will be portland type 2.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Pres. DATE 8-9-76

APPROVED BY [Signature] TITLE SUPERVISOR, DISTRICT II DATE AUG 10 1976

CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness