



LOCATE WELL CORRECTLY

## LOG OF OIL OR GAS WELL

Company J. H. Elder Address Midland, Texas  
Louis F. Root Field Grayburg State New Mexico

Well No. 3 Sec. 18 T. 17 R. 22 Meridian N.M.P.M. County Eddy

Location 660 ft.  $\frac{H}{H}$  of N Line and 660 ft.  $\frac{H}{H}$  of W Line of Section 12 Elevation (Denote feet relative to sea level)

The information given herewith is a complete and correct record of the well and all work done thereon so far as can be determined from all available records.

Signed [Signature]

Date June 13, 1941

Title Auditor

The summary on this page is for the condition of the well at above date.

Commenced drilling April 22, 1941 Finished drilling May 31, 1941

## OIL OR GAS SANDS OR ZONES

(Denote gas by (G))

No. 1, from 2530' to 2535' No. 4, from \_\_\_\_\_ to \_\_\_\_\_  
 No. 2, from 2587' to 2597' No. 5, from \_\_\_\_\_ to \_\_\_\_\_  
 No. 3, from 2625' to 2635' No. 6, from \_\_\_\_\_ to \_\_\_\_\_

## IMPORTANT WATER SANDS

No. 1, from 310' to 320' No. 3, from \_\_\_\_\_ to \_\_\_\_\_  
 No. 2, from 2035' to 2055' No. 4, from \_\_\_\_\_ to \_\_\_\_\_

## CASING RECORD

Size casing	Weight per foot	Threads per inch	Make	Amount	Kind of shoe	Cut and pulled from	Perforated		Purpose
							From—	To—	
<u>10"</u>	<u>404</u>	<u>8</u>	<u>Sm 1</u>	<u>450</u>	<u>Tap</u>				
<u>8 1/2"</u>	<u>251</u>	<u>8</u>	<u>Sm 1</u>	<u>1000</u>	<u>Tap</u>				
<u>7"</u>	<u>202</u>	<u>8</u>	<u>Sm 1</u>	<u>2592</u>	<u>Tap</u>				

## MUDDING AND CEMENTING RECORD

Size casing	Where set	Number sacks of cement	Method used	Mud gravity	Amount of mud used
<u>10"</u>	<u>450'</u>	<u>50 SAX</u>			
<u>8 1/2"</u>	<u>1980'</u>				
<u>7" OD</u>	<u>2392'</u>	<u>100 SAX</u>			<u>20 SAX</u>

## PLUGS AND ADAPTERS

Heaving plug Material \_\_\_\_\_ Length \_\_\_\_\_ Depth set \_\_\_\_\_  
 Adapters—Material \_\_\_\_\_ Size \_\_\_\_\_

## SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
<u>4"</u>	<u>Tin</u>	<u>Nitroglycerine</u>	<u>100 qts 5-31</u>	<u>2515-2540</u>		
<u>4"</u>	<u>Tin</u>	<u>Nitroglycerine</u>	<u>100 qts 5-31</u>	<u>2727-2752</u>		<u>2752'</u>

## TOOLS USED

Rotary tools were used from \_\_\_\_\_ feet to \_\_\_\_\_ feet, and from \_\_\_\_\_ feet to \_\_\_\_\_ feet  
 Cable tools were used from 0 feet to 2752' feet, and from \_\_\_\_\_ feet to \_\_\_\_\_ feet

## DATES

\_\_\_\_\_, 19\_\_\_\_ Put to producing June 15, 1941

FOLD MARK