

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other Instructions
verse side)

Modified Form No.

NIXO-3160-4

OCD

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		3a. Area Code & Phone No. (505) 748-3303	
2. NAME OF OPERATOR Marbob Energy Corporation		8. FARM OR LEASE NAME Square Lake 12 Unit	
3. ADDRESS OF OPERATOR P. O. Drawer 217, Artesia, NM 88210		9. WELL NO. 114	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit K, 1980 FSL 1980 FWL		10. FIELD AND POOL, OR WILDCAT Square Lake Grbg SA	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 12-T17S-R29E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3648' GR		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

RECEIVED

JAN 22 '90

O.C.D.

ARTESIA, OFFICE

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☒
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

12/29/89 RU, pulled rods & tbg, RIH w/6 1/8" flat bottom mill, tagged up @ 2165', started milling.

12/30/89 Drld up bridges @ 2165-2194', CO to 2250', milling on tbg, POH, ran rods & tbg, put back on pump.

1/2/90 Well still not making fluid, pulled rods & tbg, RIH w/wash pipe and 6 1/8" overshot mill, still drlg on metal, drld for 1 1/2 hrs., POH.

1/3/90 Ran rods & tbg in hole, POH laying down rods & tbg, 66-2 3/8" tbg, 85-3/4" rods. TA well.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Clerk

DATE 1/4/90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side