

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR MAP
OF COPIES REQ.
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
NMXO-3160-4

dsf

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

OCT 5 11 25 AM '90

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		3a. Area Office No. (505) 748-3303		5. LEASE DESIGNATION AND SERIAL NO. LC-065591	
2. NAME OF OPERATOR Marbob Energy Corporation		3b. Area Office No. (505) 748-3303		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Drawer 217, Artesia, NM 88210		OCT 17 '90		7. UNIT AGREEMENT NAME Square Lake 12 Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below) At surface Unit K, 1980 FSL 1980 FWL		C. F. [Signature]		8. FARM OR LEASE NAME	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3648' GR		9. WELL NO. 114	
				10. FIELD AND POOL, OR WILDCAT Square Lake Grbg SA	
				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 12-T17S-R29E	
				12. COUNTY OR PARISH Eddy	
				13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	PULL OR ALTER CASING
FRACTURE TREAT	MULTIPLE COMPLETION
SHOOT OR ACIDIZE	ABANDON*
REPAIR WELL	CHANGE PLANS
(Other)	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*
(Other)	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

9/18/90 Plugged and abandoned well as follows:

RIH w/7" pkr to 2091'. Sqzd from 2579-2100 w/100 sx Cement. Tagged plug at 2118'. Displaced hole w/salt gel to 1300'. Perfed csg at 1300'. RIH w/7" pkr and set at 1125'. Sqzd perms w/75 sx Cement. Tagged plug at 1167'. Perfed csg at 400'. RIH w/7" pkr and sqzd perms at 400' w/75 sx Cement. Tagged plug at 295'. Spot 25 sx plug at surface.

Will notify you when location is ready for inspection.

Post ID-2
10-26-90
P417

18. I hereby certify that the foregoing is true and correct

SIGNED Chonda Nelson

TITLE Production Clerk

DATE 10/1/90

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE 10-16-90

Approved by the Bureau of Land Management
for the purpose of the well and until
surface restoration is completed.

*See Instructions on Reverse Side