

NEW MEXICO OIL & GAS COMMISSION
ARTESIA, NM DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED BY

SUNDY NOTICES AND REPORTS ON WELLS
(See instructions on reverse side)

O. C. D.

ARTESIA, OFFICE

Form approved
Budget Bureau No. 42-11121.

LEASE DESIGNATION AND SERIAL NO.

LC-028785

IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Injection</u>	7. UNIT AGREEMENT NAME <u>Square Lake "12" Well</u>
2. NAME OF OPERATOR <u>Gulf Oil Corporation</u>	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR <u>P. O. Box 670, Hobbs, NM 88240</u>	9. WELL NO. <u>117</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>660' FSL + 1980' FWL</u>	10. FIELD AND TOOL, OR WILDCAT <u>Square Lake (GSA)</u>
14. PERMIT NO.	11. SEC. T. R. M. OR BLM AND SURVEY OR AREA <u>Sec. 12-T17S-R29E</u>
15. ELEVATIONS (Show whether of, at, or, etc.) <u>3644' GL</u>	12. COUNTY OR PARISH 13. STATE <u>Eddy NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☒
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	
(Other) ☐			

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Plugging & pkr. found leak in 1st csg collar below
bradenhead. Welded collar to upr. leak. Set to 500 psi-
10 min. then cut to PBTD 2555'. Reported to Mike
Williams (OCD) 7-7. GIN up inj pipe, up pkr. Circ pkr fluid
& tol backside 500# for 15 min - no press loss. Hook
up well. Began inj water.

18. I hereby certify that the foregoing is true and correct

SIGNED <u>[Signature]</u>	TITLE <u>Area Engineer</u>	DATE <u>7-16-84</u>
ACCEPTED FOR RECORD		
(This space for Federal or State office use)		
APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL <u>JUL 18 1984</u>		

Artesia, NEW MEXICO See Instructions on Reverse Side