

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NM OIL CONS COMMISSION
Drawer DD
Artesia, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Marbob Energy Corporation

3. Address and Telephone No.

P.O. BOX 227, Artesia, NM 88210 (505) 748-3303

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SEC 13 T-17-S R-29-E 660' FNL & 1980' FWL Unit C

5. Lease Designation and Serial No.

LC-028784C

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

BURCH KEELY UNIT

8. Well Name and No.

Burch Keely Unit #3

9. API Well No.

30-015 -02973

10. Field and Pool, or Exploratory Area

GRBG JACKSON SR Q GRBG SA

11. County or Parish, State

Eddy, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) 7" CIBP set @ 2360' 5-11-92
- 2) Load hole with mud
- 3) Spot 2 sacks cement on top of 7" CIBP
- 4) Perforate 7" casing @ base of salt 970' Squeeze with 50 sacks cement W.O.C
Tag cement top @ 866'
- 5) Perforate 7" casing @ top of salt @ 8-5/8" shoe 652' Squeeze with 80 sacks cement W.O.C.
Tag cement top @ 416'
- 6) Perforate 7" casing @ 50' Circulate cement to surface between 7" & 8-5/8" & open hole
leaving 7" full Set P.A. marker
- 7) Job completed 10-23-93

Part ID-2
11-17-95
P & A

14. I hereby certify that the foregoing is true and correct

Signed

Elvira L. Loh

Title

Deputy Secretary

Date

10/27/95

(This space for Federal or State office use)

Approved by

Title

Date

12/7/95

Conditions of approval, if any: