

NEW MEXICO OIL CONSERVATION COMMISSION

Effective 1-1-65

MAY 3 1979

O. C. C.
ARTESIA, OFFICE

SUNDARY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR NOTICES TO WELLS OR TO WELLS OR WELLS LACK TO A DIFFERENT RESERVOIR.
(SEE INSTRUCTIONS FOR REPORT ON FORM C-101, FOR SUCH PURPOSES.)

5a. Indicate Type of Lease

State ☒Fee ☐

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Form of Lease Name

State "J"

9. Well No.

54

10. Field and Pool, or Window

Grayburg Jackson

15. Elevation (Show whether DF, RT, GR, etc.)

12. County

Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

PLUG AND ABANDON

CHANGE PLANS

OTHER

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOBS

OTHER

ALTERING CASING

PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE FORM 1103.

We propose to plug & abandon this well using the following procedure:

Run impression block - check for top of junk.

Dependent upon impression block - possibly attempt to fish out junk or tubing.

Determine free point of 6 5/8" by stretch - if possible - pull entire string, if free.

(a) if 6 5/8" was free - run tubing and spot cement plugs as directed by OCC.

(b) if 6 5/8" partially free - pull all possible casing - run tubing & spot cement plugs as directed by OCC.

Pull 6 5/8" surface casing if possible, then spot remaining plugs as directed by OCC.

Above program is subject to change dictated by well conditions and OCC approval.

5/11/79 Pulled 1594' of tbq (line pipe + 140 tbq)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

Manager-Engineer

DATE May 2, 1979

RECEIVED BY

TITLE

SUPERVISOR, DISTRICT II

DATE

MAY 11 1979

SIGNATURES OF OTHERS, IF ANY

Notify N.M.O.C.C. in sufficient time to witness

Over

Over

Plugging

tagged To c @ 16²⁷

operated @ 1610 4 holes

runned 50 SX gauge

To c @ 1540' retains 1590' 4 SX Top

free point @ 675'

shot off 8⁵/₈ @ 669'

~~Pulled 8⁵/₈"~~

M.S.

Set Plug @ 669 Tagged Plug @ 609 could not Pull 8⁵/₈ Set 80 SX
class c @ 341' to 108' Hole in 8⁵/₈ @ 108 Set 10 SX to surface class c

Finished Plug @ 2:00 PM @ 5-27-79

