

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. 029731-AUnit Lease

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS <u>X</u>	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 10, 1948

Well No. 5 is located 660 ft. from N line and 660 ft. from E line of sec.

SW 1/4 of Sec. of 22 173 29E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Grayburg-Jackson Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3543 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Notice was given and permission received to deepen this well to approximately 3300' to test the Slaughter Pay. Upon going into the hole to deepen we found that iron had been left in the hole and not shown on any of our records. We were unable to take an impression as the top of the junk was over in the shot-hole. Our efforts to fish out were unsuccessful and we drilled by from 2616' to 2639'. Indications are that a string of tools was lost in this well and it was decided to put the well back on the pump.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Barnsdall Oil CompanyAddress Box 1,Hobbs, New Mexico

By

Title Dist. Supt.