

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1266
7. Lease Name or Unit Agreement Name G-J West Coop Unit
8. Well No. 27
9. Pool name or Wildcat Grbg Jackson SR Q Grbg SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator
Marbob Energy Corporation
3. Address of Operator
P. O. Drawer 217, Artesia, NM 88210

RECEIVED

AUG 02 '89

4. Well Location
Unit Letter K : 1650 Feet From The South
Section 22 Township 17S Range 29E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3540' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
We plugged & abandoned well as follows:

5/31/89 Set 125 sx plug @ 3260', tagged @ 2316'; set 60 sx plug @ 2300', tagged @ 2100'; set 25 sx plug @ 1800'; perfed csg @ 779', sqd w/75 sx cmt, did not tag; sptd 75 sx plug @ 800', did not tag; sptd 75 sx plug @ 800, tagged @ 785'; sptd 50 sx plug @ 785', tagged @ 780'; sptd 50 sx plug, tagged @ 758'; sptd 75 sx plug, tagged @ 335'; perfed csg @ 200', set 50 sx plug @ 248', tagged @ 260'; sptd 30 gal. plug of cmt & sand, tagged @ 203'; set 50 sx plug @ 200', tagged @ 203'; sptd 25 sx plug @ 203', tagged @ 200'; sptd 14 sx plug @ 200', tagged @ 196'; sptd 40 sx, tagged @ 75'; filled csg w/cmt. Will notify you when location is cleaned & ready for inspection.

Post ID-2
8-4-89
PFA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rhonda Nelson TITLE Production Clerk DATE 8/1/89
TYPE OR PRINT NAME Rhonda Nelson TELEPHONE NO. 748-3303

(This space for State Use)

APPROVED BY Danell Moore TITLE Geologist DATE 10/26/89
CONDITIONS OF APPROVAL, IF ANY:

