

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OFFICE FOR FARMERS
OF COPIES REQUIRED
(Other Instructions on reverse side)

Modified Form No.

NM60-3160-4

45F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

SEP 24 8 52 AM '90

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
Marbob Energy Corporation / AREA ☐ 3a. Area Code & Phone No.
(505) 748-3303

3. ADDRESS OF OPERATOR
P. O. Drawer 217, Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

330 FSL ~~2310~~ FWL

2309 (New Survey)

OCT 11 '90

A. C. D.
ARTESIA, OFFICE

14. PERMIT NO.
30-015-02476

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3546' DF

5. LEASE DESIGNATION AND SERIAL NO.

LC-028731 (A)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

M. Dodd "A" Fed.

9. WELL NO.

14

10. FIELD AND POOL, OR WILDCAT

Grbg Jackson SR Q Grbg SA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 22-T17S-R29E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We propose to plug and abandon well as follows:

Set cmt plug @ 3263-2240', tag plug, set cmt plug @ 1700-1500',
set cmt plug @ 945-745', set cmt plug @ base csg 400-500' and
set surface plug. Install dry hole marker and clean location.

Robert Chase obtained verbal approval from Shannon Shaw w/BLM
to proceed with work 9/14/90.

18. I hereby certify that the foregoing is true and correct

SIGNED

Shonda Nelson

TITLE Production Clerk

DATE 9/14/90

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

10 5 90

*See Instructions on Reverse Side