

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

1. Budget Bureau No. 1004-0135  
Expires August 31, 1985

2. LEASE DESIGNATION AND SERIAL NO.

LC-054406

3. IF INDIAN, ALLOTTEE OR TRIBE NAME

4. UNIT AGREEMENT NAME

5. FARM OR LEASE NAME

Dexter Federal

6. WELL NO.

1

7. FIELD AND POOL, OR WILDCAT

Gb/Jackson SR-Q-Gb-SA

8. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

24, 17-S, 29-E

9. COUNTY OR PARISH 10. STATE

Eddy

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

RECEIVED

JUN - 1 1992

O. C. D.

OFFICE

1. NAME OF OPERATOR

Phillips Petroleum Company

2. ADDRESS OF OPERATOR

4001 Penbrook St., Odessa, Texas 79762

3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

Unit F, 1980' FNL & 1980' FWL

4. PERMIT NO.

5. ELEVATIONS (Show whether DF, RT, GR, etc.)

Api No. 30-015-03080

3602' GR

6. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Set CIBP and TA Wellbore ☒

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

5/14/92 MI & RU. Pull rods and pump. Change well head and NU BOP. COOH w/prod. tubing. GIH with 7" CIBP set at 2185' pull up and circ. wellbore with KW-132 & fresh water 89 bbls to circulate. Press. up on casing to 550#. No leak off. Ran chart for BLM Representative. COOH with 2-3/8 workstring. Install well head connections-nipple down R.O.P. T/A complete.

Phillips requests permission to temporary abandon for 1 year.

This Approval of Temporary  
Abandonment Expires

APPROVED FOR 12 MONTH PERIOD

ENDING 5/13/93

5/13/97

8. I hereby certify that the foregoing is true and correct

SIGNED

J. M. Sanders

TITLE Supv., Reg. & Pror.

DATE 5/18/92

915/368-1665

(This space for Federal or State office use)

Original Signed by [Signature]


APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE 5/22/92

\*See Instructions on Reverse Side



RECEIVED

JUN - 1 1992

O. C. D.  
FEDERAL OFFICE