

(SUBMIT IN TRIPPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 026704-93 (b)
Unit Keely "B"

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Lees Mills, New Mexico, December 27, 1950

Well No. 12-B is located 25 ft. from N line and 25 ft. from W line of sec. 25
12-B (1/4 Sec. and Sec. No.) 17-S (Twp.) 29-E (Range) N.M.P.M. (Meridian)
Grayburg-Jackson (Field) Edgy (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On December 23, 1950, we ran 395' of 8-5/8" OD 21# Std third J-55 new National seamless casing to 403' and cemented with 75 sacks preceded by heavy mud to surface.

After allowing to stand cemented for 72 hours, we drilled plug, bailed hole down and tested water shut-off by the bailing method.

As shut-off proved complete drilling was resumed.

Cementing was done by Halliburton Oil Well Cementing Company.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company GENERAL AMERICAN OIL COMPANY OF TEXAS

Address Box 416, Lees Mills, New Mexico

By R. J. Heard
R. J. Heard
 Title Field Superintendent