

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Oil Cons. N.M. Div-Dist 2
1301 W. Grand Avenue
Artesia, NM 88210


FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993
Designation and Serial No. 8828784C
Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other
2. Name of Operator
MARBOB ENERGY CORPORATION
3. Address and Telephone No.
PO BOX 227, ARTESIA, NM 88211-0227 505-748-3303
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980 FSL 1980 FEL, SEC. 25-T17S-R29E, UNIT J



7. If Unit or CA, Agreement Designation
NMNM88525X
8. Well Name and No.
BURCH KEELY UNIT #184
9. API Well No.
30-015-03096
10. Field and Pool, or Exploratory Area
GRBG JACKSON SR Q GRBG SA
11. County or Parish, State
EDDY CO., NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

NOTIFY BLM 24 HRS BEFORE STARTING

- 1. POOH W/ RODS & TUBING
- 2. SET 7" CIBP @ 3000' (PERF 3100' - 3155') - 35' CMT ON TOP
- 3. PERF 7" @ 2036', SQUEEZE 45 SX, WOC TAG
- 4. PERF 7" @ 902' (BASE SALT 852') SQUEEZE 45 SX, WOC TAG
- 5. PERF 7" @ 486' (8 5/8" SHOE @ 480' TOP SALT 405') CIRC CMT TO SURF, WOC TAG
- 6. SPOT 60 PLUG @ SURF
- 7. CUT OFF WELL HEAD, INSTALL DRY HOLE MARKER

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

Accepted for record - NMOC



14. I hereby certify that the foregoing is true and correct

Signed *[Signature]*
(This space for Federal or State office use)

Title PRODUCTION ANALYST

Date 3/27/02

Approved by
Conditions of approval, if any:

Title

Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

RECEIVED

2002 MAR 28 AM 9:32

BUREAU OF LAND MGMT
ROSWELL OFFICE