

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

APR 12 1996

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other
2. Name of Operator
Marbob Energy Corporation
3. Address and Telephone No.
P. O. Drawer 227, Artesia, NM 88210 (505) 748-3303
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec. 25 T-17-S R-29-E 1295' FSL & 1345' FWL Unit N

5. Lease Designation and Serial No.
LC-028784C

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Burch Keely Unit

8. Well Name and No.

Burch Keely Unit #200

9. API Well No.

30-015-03107

10. Field and Pool, or Exploratory Area
Grbg Jackson SR Q GRBG SA

11. County or Parish, State

Eddy, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*.

- Set 7" CIBP @ 2950' Cap W/35" cement
- Set 7" CIBP @ 2550' Cap W/35" cement
- Perforate 7" casing @ 914' Squeeze W/60 sacks cement W.O.C. No cement in casing, Squeeze W/60 sacks cement W.O.C. No cement in casing, Squeeze W/60 sacks cement W.O.C. Cement top @ 798'
- Perforate 7" casing @ 503' Squeeze W/60 sacks cement W.O.C. Tag cement top @ 382'
- Perforate 7" casing @ 50' Circulate cement to surface leaving 7" full Set PA marker
- Job completed 3-12-96

Post FD-2
7-12-96
P&H

14. I hereby certify that the foregoing is true and correct

Signed E. K. Kleck

Title Dist. Secty

Date 4-10-96

(This space for Federal or State office use)

Approved by E. K. Kleck

Title Dist. Secty

Date 5/16/96

Conditions of approval, if any: