

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

LC-028784-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Keely "B" Federal

9. WELL NO.

15

10. FIELD AND POOL, OR WILDCAT

Gb/Jackson SR-Q-Gb-SA

11. SEC., T., R., M., OR BLK. AND
SUBST. OR AREA

Sec. 26, 17-S, 29-E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Phillips Petroleum Company

3. ADDRESS OF OPERATOR

4001 Penbrook St., Odessa, Texas 79762

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit I, 2615' FSL, 1295' FEL

14. PERMIT NO.

API No. 30-015-30125

15. ELEVATIONS (Show whether SP, RT, OR, etc.)

3593' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Set CIBP & TA wellbore

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-2-92: MI & RU. NU BOP. GIH with scraper and 2-3/8" workstring to 2845'. COOH. GIH with 7" CIBP on workstring to 2832'. Set plug. Pull up 1 joint. Circulate wellbore with 110 bbl packer fluid (Tretolite KW-132 and water). Press up casing to 500 lbs. No press. loss. Contact BLM - Rep Mr. Don Early on location. Ran press. recorder to 500# for 15 min. No leakage. Release press. COOH with workstring laying down. NU wellhead. T/A complete.

Phillips request permission to temporarily abandon for one year.

APPROVED FOR 12 MONTH PERIOD

ENDING 6/2/93

This Approval of Temporary
Abandonment Expires

6/02/97 G.W.

18. I hereby certify that the foregoing is true and correct

SIGNED

L. M. Sanders

TITLE Supv., Regul. & Proration

DATE 6/5/92

(915) 368-1488

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

6/16/92

*See Instructions on Reverse Side

