

Form 3160-5  
(July 1989)  
(Formerly 9-331)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING  
OFFICE FOR NUMBER  
OF COPIES REQUIRED  
(Other instructions on reverse  
side)

BLM Roswell District  
Modified Form No.  
NM060-3160-4

CLSF

RECEIVED

5. LEASE DESIGNATION AND SERIAL NO.  
LC-028775-B

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.)

JUN 1 1992

O. C. D.

OFFICE

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR SOUTHLAND ROYALTY COMPANY		8. FARM OR LEASE NAME RJU TR 2A	
3. ADDRESS OF OPERATOR P.O. Box 51810, Midland, TX 79710-1810	3a. AREA CODE & PHONE NO. 915-688-6906	9. WELL NO. 8	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface K, 1980' FSL & 1980' FWL		10. FIELD AND POOL, OR WILDCAT GRAYBURG JACKSON 7 RVRS	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 27, T-17-S, R-29-E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3526' GR	12. COUNTY OR PARISH EDDY	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☒  
☐  
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

5/08/92 RIH W/ 6-1/4" BIT TO 2338.55'. SET DN ON CIBP. COULD NOT DRIVE DN. SPOT CMT PLUG W/ 50 SX CLASS "C" CMT W/ 2% CACL2. CALC TOP @ 2048'.

5/09/92 RIH & PERF 7" CSG @ 710'. RU TO RUN CMT RET. RIH TO 610'. PUMP 40 SX CLASS "C" CMT BELOW RET. POOH W/ RET. CAP W/ 10 SX. CALC TOP 550'. RIH & PERF CSG @ 350'. RIH W/ PKR TO 60', PUMP 150 SX CLASS "C" CMT BELOW 7" X 8-5/8". WOC TO TAG. RIH & TAG CMT @ 110'. PUMP 20 CLASS "C" CMT BACK TO SURFACE. WELL P&A'D.

Approved as to  
Liability and  
Surface Rights

Post ID-2  
6-5-92

18. I hereby certify that the foregoing is true and correct

SIGNED

*Ramon Scholz*

TITLE

PRODUCTION ASST.

DATE

5-29-92

(This space for Federal or State office use)

APPROVED BY

*Ramon Scholz*

TITLE

DATE

6-9-92

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side