

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Continental Oil Company	8. Farm or Lease Name State S-30
3. Address of Operator P. O. Box 460, Hobbs, New Mexico	9. Well No. 2
4. Location of Well UNIT LETTER F 2310 FEET FROM THE north LINE AND 1254 FEET FROM THE west LINE, SECTION 30 TOWNSHIP 17-S RANGE 29-E NMPM.	10. Field and Pool, or Wildcat Empire Abo Field Abo Pool
15. Elevation (Show whether DF, RT, GR, etc.) 3643 Gr.	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In order to increase production in the subject well, it is proposed to acidize the existing perforations using the following procedure:

1. Kill well with oil.
2. Unseat packer & spot acid over perfs 6276-6300'.
3. Acidize w/1500 gals 15% LSTNE acid using ball sealers.
4. Swab back acid water & place on production.
5. Take potential test.

Your approval of the above work is requested.

RECEIVED

JUN 23 1965

O. C. C.
ARTERIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED SIGNED: ROBERT GAULT III TITLE Staff Supervisor DATE 6-17-65

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE JUN 23 1965

CONDITIONS OF APPROVAL, IF ANY:

NMOCC-6 SLO LPT