Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89		
DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO.		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease STATE X FEE		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. E-537		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name		
1. Type of Well: OL WELL X WELL	OTHER	RECEIVED	C-State		
2. Name of Operator Marbob Energy Corpora	ation	SEP 2 4 1991	8. Well No.		
3. Address of Operator P. O. Drawer 217, Ar	tesia, NM 82810	O. C. D.	9. Pool name or Wildcat Grbg Jackson SR Q Grbg SA		
ARTESIA OFFIC: ARTESIA OFFIC: Unit Letter :2310Feet From TheSouthLine andFeet From The EastLine					
Section 33 Township 17S Range 29E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 10. Elevation (Show whether DF, RKB, RT, GR, etc.)					
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
	PLUG AND ABANDON	X REMEDIAL WORK			
	CHANGE PLANS				
PULL OR ALTER CASING CASING TEST AND CEMENT JOB					
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed					

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any pa work) SEE RULE 1103.

We propose to plug and abandon as follows: Set cmt plug from PBTD to 2700'. Tag plug @ 2700', set cmt plug from 2400-2250' (top? Grayburg). Set cmt plug from 2000-1850' (top Queen). Perf csg @ **Perfit**. On. 850' (base salt) and attempt to circ cmt to surface, leave csg full cmt and install dry hole marker and clean location. In the event we cannot circ cmt to surface we will perf csg @ 250' and circ cmt inside and out w/cmt.

+ gel between plugs

I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE ROBIN Am. th	ige and belief. TILE Production Clerk	DATE9/20/91		
TYPE OR PRINT NAME Robin Smith		TELEPHONE NO.748-3303		
(This space for State Use) * As Noted Above AFTROVED BY	— тпе — (1), †39 бу з (#SPECTBR	DATE _/0-1-91		
CONDITIONS OF APPROVAL, IF ANY:				
plugging	· · · · · •			