

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION RECEIVED NO.

L C 028775 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

14 1980

7. UNIT AGREEMENT NAME

Robinson Jacks Office

8. FARM OR LEASE NAME

Tract 1 A

9. WELL NO.

12

10. FIELD AND POOL, OR WILDCAT

Grayburg-Jackson

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 34, T 17 S - R 29 E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒

Injection Well

2. NAME OF OPERATOR

Southland Royalty Company

3. ADDRESS OF OPERATOR

1100 Wall Towers West, Midland, Texas 79701, NEW MEXICO

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface

660' FNL &amp; 654' FEL Sec. 34, T 17S - R 29 E

Eddy County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3558 Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☒ALTERING CASING ☐ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8-25-77 Riggged up pulling Unit.  
Pulled all packers, regulators, and tubing.  
Found hole in top reg. sub. also holes in 3 jts, below bottom packer. Dressed packers and reg. Tubing tested back in hole.  
Found leak in 1 jt., 12 jts. down from top.

8-30-77 Ran tubing, pkrs and regs. back in well. Spaced out packers.  
Returned well to injection status.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Donald R. Cray*

TITLE

District Production Engineer

DATE

4-9-80

(This space for Federal or State office use)

GEORGE H. SILWANE

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APR 11 1980