RJU TR 1A #2 PLUG AND ABANDON CONT.

8/9/93: RIH TAGGED CSG STUB @ 955'. NO CMT ON TOP. PMPED 30 SXS CMT. WOC. CONTACTED BLM AND WAS GIVEN THE OK TO DUMP PEA GRAVEL. DMPED 4 YDS PEA GRAVEL DOWN CSG. RIH TAGGED TOP OF GRAVEL @ 870. PMPED 30 SXS CMT ON TOP. WOC. RIH TAGGED CMT @ 896. RIH W/TBG OPEN ENDED TO 896. PMPED 30 SXS CMT. 8/10/93: RIH TAGGED PLUG @ 862. RIH W/TBG. PMPED 20 SXS CMT AT 850. WOC. RIH TAGGE DPLUG @ 827. FILLED HOLE W/FRESH WATER. RU WIRELINE. RIH TO 760. PERFORATED 8 HOLES. POOH W/WIRELINE. WELDED ON HEAD. NU BOP. TRIED TO ESTABLISH CIRCULATION. WELL WOULD NOT. PMPED 50 SXS CMT AT 750. WOC 8/11/93: RIH TAGGED PLUG AT 636. TRIED TO LOAD HOLE. HOLE WOULD NOT LEA.D RU WIRELINE. PERFORATED AT 360. TRIED TO ESTABLISH CIRCULATION, WOULD NOT. PMPED 130 SXS CMT . WOC. RIH TAGGED PLUG AT 130. LOADED HOLE. RIH W/WIRELINE PERFORATED AT 130. PMPED 100 SXS CMT. WOULD NOT CIRCULATE. WOC. 8/12/93: RIH TAGGED PLUG AT 117. COULD NOT LOAD HOLE. PMPED 30 SXS CMT WOC. RIH TAGGED PLUG AT 117. PMPED 30 SXS CMT. WOC.

8/15/93: RIH TAGGED PLUG AT 117. PMPED 30 SXS CMT.

8/16/93: RIH TAGGED PLUG AT 117. PMPED 30 SXS CMT

8/17/93: RIH TAGGED PLUG AT 117. PMPED 30 SXS CMT

8/18/93: RIH TAGGED PLUG AT 117. MIXED CACL2 W/CMT PMPED 20 SXS. WOC. MIXED CACL2 W/CMT. PMPED 30 SXS WOC. STARTED PMPING CMT. SHOWED SIGNS OF CIRC. PMPED 120 SXS CMT.

8/19/93: RIH TAGGED PLUG AT 117. GIVEN OK BY BLM TO DUMP 20' PEA GRAVEL DOWN 10" AND FILL W/CMT TO SURFACE. PMPED 55 SXS CMT FILLED 10" CUT OFF CSG 3' BELOW SURFACE. INSTALLED P & A MARKER.

LOCATION HAS NOT BEEN CLEANED AS OF THIS DATE. WILL FILE FOLLOWUP SUNDRY UPON COMPLETION OF CLEAN UP.